

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		3. LEASE DESIGNATION AND SERIAL NO. CONTRACT 82	
2. NAME OF OPERATOR Jerome P. McHugh		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache	
3. ADDRESS OF OPERATOR P.O. Box 809 Farmington, NM 87499		7. UNIT AGREEMENT NAME ---	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 830' FNL, 1850' FEL		8. FARM OR LEASE NAME Burke	
14. PERMIT NO		9. WELL NO. #2	
15. ELEVATIONS (Show whether OF, RT, CR, etc.) 7068' GL		10. FIELD AND POOL, OR WILDCAT Choza Mesa PC	
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5, T28N, R3W	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE NM	

16.

Check Appropriate Box To Indicate Nature of Notice Report or Operation

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

WATER SHUT-OFF	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>		<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(Note: Report on multiple completion on Well Completion or Well Test on Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plans to P&A well previously submitted are to be modified per verbal permission of Leonard Bixler as follows:

1. Move in and rig up pulling unit; install BOP.
2. Circulate hole with water. Pull and lay down 1-1/2" tubing. Run casing bond log. Pick up 2-3/8" tubing work string.
3. Spot 15 sack Class "B" cement plug across perms at 3,705' - 3,711' and 3,715' - 3,723'. Plug interval to be 3,774' to 3,574'.
4. Spot 27 sack Class "B" cement plug at 3,532 - 3,300' inside casing opposite Ojo Alamo.
5. Cut off 4-1/2" casing @ 1,540'. Pull free casing. Spot 40 sack Class "B" cement plug @ 1,612'.
6. Spot 60 sack Class "B" cement plug @ 912' KB.
7. Spot 136 sack Class "B" cement plug @ 276' to surface.
8. Cut off surface casing 4' below ground level and install dry hole marker.
9. Clean up and restore location per instructions from surface management agency.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sam Johnson

TITLE

Petroleum Engineer

DATE

11 April 1990

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

John Kelly
11 April 1990
MANAGER, RESOURCE AREA

*See Instructions on Reverse Side