Form 9-331 Dec. 1973

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Form Approved.		
	Budget Bureau No. 42-R1424		
[5. LEASE		
1	Contract 83		
i	The second secon		
1	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
	Jicarilla Apache		
į	7. UNIT AGREEMENT NAME		
nt			
	8. FARM OR LEASE NAME		
	Jer		
	9. WELL NO.		
	1		
	10 FIELD OD WILLDOAT MANS		
	10. FIELD OR WILDCAT NAME		
	Wildeat ChozA //ISA PC		
	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
7	AREA		
.	Sec 18 T28N R3W		
	12. COUNTY OR PARISH 13. STATE		
	Rio Arriba NM		
]	14. API NO.		
Ε,			
	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
	7220' GL 7232' RKB		
	1220 GL 1232 RRD		

	o real filta ripaene		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME		
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME		
1. oil gas	Jer		
well well other dry hole	9. WELL NO.		
2. NAME OF OPERATOR	1		
Jerome P. McHugh	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR	Wildeat Maza Mara He		
Box 208, Farmington, NM 87401	CHOCH THEST		
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	· ·		
below.)	Sec 18 T28N R3W		
AT SURFACE: 840' FSL - 1190' FEL	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL:	Rio Arriba NM		
AT TOTAL DEPTH:	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
•	7220' GL 7232' RKB		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	TEEO GE TESE TRO		
TEST WATER SHUT-OFF	$\frac{1}{2}$ (4)		
FRACTURE TREAT			
SHOOT OR ACIDIZE	IVEM		
REPAIR WELL	(NOTE: Report results of multiple completion or zone		
PULL OR ALTER CASING [AND A DESCRIPTION OF THE PUBLIC PROPERTY OF	chart on Form 9-330.)		
MULTIPLE COMPLETE	7 1985		
CHANGE ZONES	λ.1. Β .11.		
ABANDON*	N. DIV.		
(other) DIS	T 3		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* APPROVED			
This well was plugged and abandoned in the following manner: AS AME			
1. Spotted 36 sx cement plug (42.48 cu ft) 4	115' to 3640' JAN 101985		
2. Shot off 4-1/2" csg @ 1533'			
2. 31100 011 1 1/2 439 6 1000	M. MILLENBACH		
3. Spotted 20 sx (23.6 cu ft) plug across cs	g stub AREA MANAGER		
4. Spotted 28 sx (33.04 cu ft) plug @ bottom of surface casing @ 200'			
 Installed dry hole marker with 3 sx cemen Cement work complete 10-8-79. 	t, filled pits and cleaned location.		
Subsurface Safety Valve: Manu. and Type	Set @ Ft.		
18. I hereby certify that the foregoing is true and correct			
SIGNED JIM Jacobs (This space for Federal or State office use)			
(This space for Federal or State off	nce use)		
APPROVED BY TITLE DATE			
as to plugging of the well bore.	(\frac{1}{2} \frac{1}{2} \frac{1}{4} \frac		

Approved Liability under bond is retained until surface restoration is completed.

. .

ae Instructions on Reverse Side

NMOCD