5-USGS (Durango)	l-McHugh l-Phillips l-N	Northwest Pipeline 1-	-Fi.le
Form 9-331	UNITED STATES	SURMIT IN TRIPLICATE®	Form approved.
(May 1963) DEPARTMENT OF THE INTERIOR verse side) Output (Other instructions on re-			Budget Bureau. No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
DLI	GEOLOGICAL SURVEY		Contract 83
			G. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			Jicarilla Apache 12 1
1.			7. UNIT AGREGMENT NAME = = = =
OIL GAS X	OTHER		TO THE STATE OF TH
2. NAME OF OPERATOR		•	8. FARM OR LEASE NAME. NEW S
Jerome P. McHugh			Jer school by the state
3. ADDRESS OF OPERATOR			9. WELL NO. 2. F. T.
P. O. Box 234, Farmington, NM 87401			2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 			10. FIELD AND POOL, OR WILDCAT
At surface			Choza Mesa
1850' FNL - 1700' FEL			11. SEC., T., B., M., OR BLK. AND.
			To the state of th
	15. ELEVATIONS (Show whether D	VI TITL OR AND A	Sec. 7-T28N R3W 12
14. PERMIT NO.			五名景意 曾 出口人声
	7340	· GR	Rio Arriba L' NM E
16. C h	reck Appropriate Box To Indicate 1	Nature of Notice, Report, or C	Other Data를 풀 풀 를 돌릴을 들
NOTICE	OF INTENTION TO:	paraua (UNIX REPORT OF STATE STATE OF
	PULL OR ALTER CASING	WATER SHUT-OFF	SEPAIRING WELL
TEST WATER SHUT-OFF	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERINO CASINO
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDON MENT
REPAIR WELL	CHANGE PLANS	(Other) CSG	
(Other)	_	(Note: Report results Completion or Recomp	s of multiple completion on Well 5 = letion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPI proposed work. If well i nent to this work.) *	is directionally drilled, give subsurface loca	ations and measured and true vertice	including estimated date of starting any all depths for all markers and zones perting any and any any and any any and any any and any
6-20-78	TD 4365'. Ran IES and opipe. Running 4-1/2" c		Laid down drill
6-21-78	Ran 108 jts 4-1/2" OD 10 set @ 4362' RKB. Cement gals CW-100 chemical was w/4% gel w/12-1/2# gilson job. Reciprocated pipe pressure 750 psi. Float*Note: HOWCO frac baff.	ted by Dowell. Prefl sh. Cemented w/150 sx onite per sx followed ite per sx. Good mud OK while cementing. t held OK. POB 8:50 le @ 4215'.	ushed hole w/420 50-50 posmix by 150 sx class xeturns throughout Maximum cementing a.m. 6-20-78. Indicate the submerial of
SIGNED STAR	fach TITLE_	Agent	
Jim i	Ja/CODS State office use)		
(This space for Federal or	Sure onice use)		Census Anna 1 Ce
APPROVED BYCONDITIONS OF APPROV	TITLE		DATE TO SEE