

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. SF 078417
2. Name of Operator Conoco, Inc.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 10 Desta Dr. Ste 100W, Midland, TX 79705 (915) 686-6548	7. If Unit or CA, Agreement Designation San Juan 28-7
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1670' FSL & 1060' FEL Sec. 21, T-28N, R-7W	8. Well Name and No. 1947
	9. API Well No. 30-039-22626
	10. Field and Pool, or Exploratory Area Blanco Mesaverde
	11. County or Parish, State Rio Arriba, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent <input type="checkbox"/> Subsequent Report <input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Abandonment <input checked="" type="checkbox"/> Recompletion <input type="checkbox"/> Plugging Back <input type="checkbox"/> Casing Repair <input type="checkbox"/> Altering Casing <input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans <input type="checkbox"/> New Construction <input type="checkbox"/> Non-Routine Fracturing <input type="checkbox"/> Water Shut-Off <input type="checkbox"/> Conversion to Injection <input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to recomplete this Dakota completion to the Blanco Mesaverde Pool by the following procedure:

1. Set a CIBP in the 4-1/2" casing @ 7000'.
2. Perforate lower Mesaverde formation (Point Lookout interval) with 10 holes @ 5140', 5145, 5158, 5168, 5197, 5235, 5258, 5238, 5375, 5405.
3. Perforate upper Mesaverde formation with 29 holes from 5996'-5118'.
4. Fracture stimulate above perforations.
5. Perforate upper Mesaverde formation with 26 holes from 4720'-4936'.
6. Fracture stimulate perforations in 5. above.
7. Clean out wellbore and put on production.

The Dakota completion in this wellbore is not being permanently abandoned. Application to downhole commingle the Dakota and Mesaverde completions will be made when sufficient Mesaverde production history has been acquired.

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Sr. Conservation Coordinator

(This space for Federal or State office use)

Approved by _____ Title _____

Conditions of approval, if any: _____

Hold C-104 For New Plat # 1944

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any false statement or representations as to any matter within its jurisdiction.

Certificate Number