

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

CONOCO INC.

3. Address and Telephone No.

10 DESTA DR. STE. 100W, MIDLAND, TX. 79705-4500 (915) 686-5424

4. Location of Well (Footage, Sec., T. R. M. or Survey Description)

1010' FNL, 320' FEL, Sec. 33, T28N, R7W

A

5. Lease Designation and Serial No.

SF 078498

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

San Juan Unit 28-7

8. Well Name and No.

191E

9. API Well No.

30-039-23753

10. Field and Pool, or Exploratory Area

Mesaverde

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Repon
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracrunng
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Repon results of multiple completion well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to recomplete this well to the Mesaverde by the following procedure:

1. Set CIBP at 5300' to isolate Dakota perforations.
2. Perforate Point Lookout from 4887' - 5277', 31 total holes; treat with 500 gals 15% HCL and frac.
3. Set CIBP at 4850'; perforate Menefee from 4596' - 4792', 23 total holes; treat with 500 gals 15% HCL and frac.
4. Set CIBP at 4500'; perforate Cliffhouse from 4284' - 4410', 27 total holes; treat with 500 gals 15% HCL and frac.
5. Drill out all CIBPs, clean out well to PBTD and put on production.

Application for Downhole Commingling of Mesaverde and Dakota has previously been submitted.

RECEIVED
MAR 25 1997
OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed

Jerry W. Hoover

Title

Jerry W. Hoover
Sr. Conservation Coordinator

Date

3-4-97

(This space for Federal or State office use)

Approved by *J. D. Spencer*
Conditions of approval if any:

Title

Date

MAR 21 1997

BLM(6), JWH,

FILE ROOM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

NMOCD

Certificate Number