UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells	
1. Type of Well GAS	5. Lease Number SF-0795290A 6. If Indian, All. or Tribe Name
	7. Unit Agreement Name
2. Name of Operator MERIDIAN OIL	San Juan 28-5 Unit 8. Well Name & Number San Juan 28-5 U 230
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No. 30-039-25364
4. Location of Well, Footage, Sec., T, R, M 1290'FNL, 2314'FEL Sec.25, T-28-N, R-5-W, NMPM	10. Field and Pool Basin Ft Coal/ Tapacitos PC Ext 11. County and State Rio Arriba Co, NM
Recompletion	c_ Change of Plans New Construction Non-Routine Fracturing
Final Abandonment Casing Repair Altering Casing Other -	Water Shut off Conversion to Injectio
13. Describe Proposed or Completed Operations It is intended to set 8 5/8", 24.0#, K-55 surface casing to approximately 640' at calcium chloride and 0.25 pps flocele (543 cu.ft.). Cement will be calcium. DECE JUN -	DOUTE DOUTE DE LE CIRCULAÇÃO SULTACE. 1 V E D 6 1994 No DUVo
14. I hereby certify that the foregoing is true and Signed May Madheed Title Regulatory A	
(This space for Federal or State Office use)	Date
APPROVED BY Title CONDITION OF APPROVAL, if any:	APPROVED
	3.1. 100.4

NMOCD

PICTRICT MANAGER