UNITED STATES

DEPARTMENT OF THE INTERIOR RECEIVED

BUREAU OF LAND MANAGEMENT		
Sundry Not:	ices and Reports Sta ANGLIS []]	2: 47
1. Type of Well GAS	070 FARMINGTO RECEIVED	N, NW 5. Lease Number SF-079521A 6. If Indian, All. or Tribe Name 7. Unit Agreement Name
2. Name of Operator MERIDIAN OIL 3. Address & Phone No. of Operator	OIL CON. DIV.	San Juan 28-5 Unit 8. Well Name & Number San Juan 28-5 U #235
PO Box 4289, Farmington, NM 4. Location of Well, Footage, Se 1850'FSL, 1850'FWL, Sec.28, 5	87499 (505) 326 9700 ec., T, R, M	9. API Well No. 30-039-25427 10. Field and Pool Basin Frt Coal/
		So Blanco Pictured Cl 11. County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INI Type of Submission Notice of Intent X Subsequent Report	Type of Action Abandonment Char Recompletion New Plugging Back Non- Casing Repair Wate	nge of Plans Construction Routine Fracturing er Shut off
Final Abandonment	Altering CasingConv _X_ Other -	version to Injection
cmt w/1.5 $rak{8}$ Howo w/125 sx Class Flocele (153 cu	30'. Ran logs. 1/2" 10.5# K-55 STC csg, set co suds, 5 pps Gilsonite, 0.25 "B" cmt w/2% calcium chloride 1.ft.) Circ 5 bbl cmt to surfa	@ 3629'. Cmtd w/420 sx Class "B" pps Flocele (512 cu.ft.). Tailed, 5 pps Gilsonite, 0.25 pps ce. Cmtd cap w/125 sx Class "B" ND BOP. NU WH. RD. Released rig
\mathcal{C}	foregoing is true and correct Title Regulatory Affairs	Date 8/18/94
(This space for Federal or State APPROVED BY CONDITION OF APPROVAL, if any:	e Office use)Title	Date CORRECORD
		AUG 3 o 1994

FARMINGTON DISTRICT OFFICE Sept.