CONFIDENTIAL

Altering Casing

Other: CIBP's

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

5. Lease Designation and Serial No.

Conversion to Injection

Disnose Water

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allotte or Tribe Name Use "APPLICATION FOR PERMIT --" for such proposals. Jicarilla Apache Tribe 7 If Unit or CA Agreement Designation SUBMIT IN TRIPLICATE 1 Type of Well N/A Oi Wet X Gas Wet 2. Name of Operator 8. Well Name and No. Mallon Oil Company Jicarilla 28-02-11 No. 1 3 Address and Telephone No 9. Well API No. P.O. Box 2797 Durango, CO 81302 30-039-26038 10. Field and Pool, or Exploratory Area Cabresto Canyon; Nacimiento Ext. 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 950' FNL and 2050' FWL (NE NE) Unit C 11. County or Parish, State Sec. 11, T28N-R02W Rio Arriba, New Mexico CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this zone.)*

Final Abandonment Notice

Malon Oil Company perforated the Cabresto Canyon; Ojo Alamo Ext. at 3466'-3474 with 4 JSPF(32 holes). Acidize with 600 gal 7-1/2% HCL. Frac 29,220 lbs 12/20 sand. Set CIBP at 3400' Test CIBP to 1000 psi. Perforate 3234'-3258' with 4 JSPF (96 holes). Acidize with 1500 gal 7-1/2% acid. CIBP set at 3215, test CIBP to 1000 psi.

Perforate the Cabresto Canyon; Nacimiento Ext. at 3003'-3012', 3024'-3034', 3097'-3117', Perforate the Cabresto Canyon; Nacimiento Ext. at 3003'-3012', 3024'-3034', 3097'-3117', 3153'-3166' with 1 JSPF (52 holes). Acidize with 3500 gal 7-1/2% HCL. Set CIBP at 2990', test to 1000 psi. Perforate 2891'-2898', 2907'-2912', 2920'-2940' with 1 JSPF (32 holes). Acidize 2200 gal_ 7-1/2% HCL acid. Set CIBP at 2875' test to 1000 psi. Perforated 2788'-2798', 2817'-2832' with 2 JSPF (50 holes). Acidize 1500 gal 7-1/2% HCL. Shut-in-up hole completion.

i hereby certify that the foregoing is true and correct							
igned	Christy Siornano	Title	Production Secretary	Date	6-8	99	<u>Z_</u>
	REFEDERAL OR STATE OFFICE USE;		Lands and Mineral Resource)E \	UIN 1	7	10°

Title 18 U. S. C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as

as to any matter within its jurisdiction