(April 1952)					
-					
		3	1		
			1		
					

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR

•	Approval expires 12-31-60.			
Indie	n Agency Navajo			
•				
Allot	toe			
موجما	No. I-149-Ind846			

GEOLOG	CAL SURVEY
SUNDRY NOTICES A	ND REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFFX SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF REDRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY
i de la companya de	December 17, 1 19.62
Linda Well No. 1-31 is located 840 ft. from	$ \left\{ \begin{array}{c} X \\ S \end{array} \right\} \text{ line and } \begin{array}{c} 790 \text{ ft. from } \left\{ \begin{array}{c} X \\ W \end{array} \right\} \text{ line of sec. } \begin{array}{c} 31 \\ \end{array} $
SW / 4 Sec. 31 27N	8W NMPM (Range) (Meridian)
Ballard Pictured Cliffs San Ju (County of Blanco Mesaverde The elevation of the derrick floor above sea lev	r Subdivision)
——————————————————————————————————————	s, weights, and lengths of proposed easings; indicate mudding jobs, coments, SURVE U. S. GEOLÓGICAL SURVE FARMINGTON, NEW MEXIC
hole to 4606' (TD). Ran 140 joints Float collar at 4572' KB. Stage co with 95 sx. Cemented through sta	/ KLULITED /
	DEC1 7 1962 OIL CON. COM.
•	writing by the Geological Survey before operations may be commenced ST,
Company Consolidated Oil & Gas,]	inc.
Address 4150 E. Mexico Avenue	
Denver 22, Colorado	By UX/Williams)
	Title Chief Engineer
W. S. GOVEPHNENT	PRINTING OFFICE 16-84976-8