



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office SE
Lease No. 081087
Unit N

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

7-19, 1958

McAdams
Well No. 4 is located 990 ft. from S line and 1650 ft. from W line of sec. 34
SW 34 (1/4 Sec. and Sec. No.) 27N 10W NMPM
(Twp.) (Range) (Meridian)
Angels Peak Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6716 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perf Dakota from 6914-50 & 6974-6994 with 2 shots per foot. Sand oil fractured with 740 bbls & 25,000 # sand. Set bridge plug at 6400. Perf Gallup from 6236 to 6248 1/2 with 4 shots per foot. Sand oil fractured with 700 bbls oil and 17,000# sand. Drilled bridge plug with gas. Hole cleaned itself. Set Baker Model D Prod. packer at 6845. Ran Camco side door choke to 6835, with 91' tubing below packer. Well tested 13,000 MCF with both zones open thru 7". Shut in for pipeline.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company W. R. Weaver
Address A. N. Brown
Room 337 U. S. National Bank Bldg.
Denver 2, Colorado
By Jay J. Harris
Title Geologist