

New Mexico  
OIL CONSERVATION COMMISSION  
Aztec, New Mexico

August 6, 1958

Mr. Jay J. Harris  
801 Ridgecrest Drive S.E.  
Albuquerque, New Mexico

Dear Mr. Harris:

The original surveyor's plat submitted on W.R. Weaver #2 McAdams well located in the SE $\frac{1}{4}$  Section 34-27N-10W indicates the well was located 1100 feet from the South line and 1010 feet from the East line; however when application for dual completion order was made on this well the location was given as 1650 feet from the North line and 990 feet from the East line of Section 34. We received a letter from Mr. Porter correcting footage location. He indicates that it is located 990 feet from the South and 990 feet from the East lines of Section 34.

If the well is located different than shown on the original surveyor's plat, i.e. 1100 feet from the South and 1010 feet from the East, please submit a corrected plat showing where the well is located.

Yours very truly

Emery C. Arnold  
Supervisor, District #3

ECA:hs

cc: Mr. A. L. Porter  
OCC, Santa Fe, N.M.