

11/12/57

F. Loc. 2310/N; 990/E Elev. 5863 GL Spd. 11-18-57 Comp. 11-29-57 TD 5103 PB 3057
 Casing S. 8 5/8 @ 313 W 230 Sx. 5 1/2 @ 5102 W 185 Sx. Pr. @ W Sx. T. 2 3/8 @ 5023
 Csg. Perf. 4776-4786 Prod. Stim. So F Perf-4986-5005 (22,000 ft) 22,000 ft

I.P. 253 BO/D After Hrs. SICP PSI After Days GOR Grav. 1st Del. 5/6

TOPS		NITD	Well Log	TEST DATA						
				Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-102	Plat	DATE	GOR	BBLs	DATE	GOR	BBLs	
Fruitland		C-103	Electric Log							
Pictured Cliffs	<u>1173</u>	C-104	C-110 1-6-58	<u>5/29/58</u>	<u>1638</u>	<u>61</u>	<u>11/20/78</u>	<u>24881</u>	<u>1</u>	<u>124/3005R</u>
Cliff House	<u>2020</u>			<u>5/19/59</u>	<u>11413</u>	<u>8</u>	<u>8/14/79</u>	<u>14000</u>	<u>1</u>	
Menutee		Ditr	Dfa	<u>3/17/60</u>	<u>4776</u>	<u>17</u>	<u>12/79</u>	<u>S.I.</u>		
Point Lookout	<u>3700</u>	Datr	Dac	<u>4/19/60</u>	<u>8628</u>	<u>7</u>	<u>5/80</u>	<u>S.I.</u>		
Mancos	<u>3905</u>	Remarks		<u>5/26/61</u>	<u>7709</u>	<u>11</u>	<u>8/31/81</u>	<u>FSM</u>	<u>0</u>	
Gallup	<u>4758</u>	Prev. Gulf-Gallegos Fed. #2		<u>4/25/62</u>	<u>14640</u>	<u>5</u>	<u>11/19/81</u>	<u>FSM</u>	<u>1</u>	
Dakota		/Skelly Oil Co.		<u>5/24/63</u>	<u>14600</u>	<u>5</u>	<u>6/82</u>	<u>SI</u>		
Morrison		/GGSU #11		<u>5/19/64</u>	<u>13750</u>	<u>4</u>	<u>6/85</u>	<u>SI</u>		
Entrada		repaired hole in casing @ 2250'		<u>5/5/65</u>	<u>27000</u>	<u>2</u>				
2nd Gallup	<u>4875</u>	Plugback Gal 8-16-85		<u>10/1/69</u>	<u>15000</u>	<u>9</u>				
3rd Gallup	<u>4985</u>	/Gallegos Fed. #2		<u>8/5/77</u>	<u>5230</u>	<u>1</u>				
Larman	<u>5051</u>	/Gulf Oil Co.		<u>5/18/78</u>	<u>16071</u>	<u>2</u>	Disconnect 2-4-82			

GallegosGal c. SJ c. 31 T 27N D 12W H A Dugan Prod. Corp. 1 June ' Gee Gee No 1