Form 9-331 (May 1983)	UNITED STATES SUBMIT IN TRIPLICATE*		Form approved. Budget Burcau No. 42-R1424.		
•		MENT OF THE INTE	RIOR verse side)	5. LEASE DESIGNATION	AND BERIAL NO.
	GEOLOGICAL SURVEY			SF 080117 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
. (Do not		ICES AND REPORTS	ON WELLS in back to a different reservoir. h proposals.)	o. IF INDIAN, ALLOTTON	OR TRIBE NAME
i.		7. UNIT AGREEMENT NAME			
WELL	WELL OTHER		•	Huerfanito	
2. NAME OF OPE		8. FARM OR LEASE NAME			
El Pas	o Natural Gas	Huerfanito			
3. ADDRESS OF	PERATOR	9. WELL NO.			
P. O. Box 990, Farmington, New Mexico 87401				74	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface				10. FIELD AND FOOL, OR WILDCAT Basin Dakota	
	1850'/N, 150	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
				Sec. 34, T27N, R9W	
14. PERMIT NO.		15. ELEVATIONS (Show whether	r DF, RT, GR, etc.)		
		6433' GL		San Juan	New Mexic
16.	Check A	opropriate Box To Indicate	Nature of Notice, Report, or C	ther Data	
NOTICE OF INTENTION TO:				EQUENT REPORT OF:	
TEST WATER	SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	
FRACTURE T	EAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	
* BHOOT OR A	IDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	T*
REPAIR WEL		CHANGE PLANS	(Other) (Nore: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		
(Other)	DAGED OF COLUMN PERSONS	Entrione (Clearly state all parti	neut details and give pertinent dates.	including estimated date	of starting any
proposed v	vork. If well is directi	onally drilled, give subsurface l	ocations and measured and true vertica	l depths for all markers	and zones perti-
nent to thi	work.)			•.	



8. I hereby certify that the foregoing is five and correct signed	TITLE Production Engineer	DATE11/22/75
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE