	No. 42-R358.4
	12-31-60.

(I	Feb. 1	961)	

Form 9-881a

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Third an exhirm 19-01-00									
Land Office	Santa Fe								
	M 03603 A								
11_14 S	E <del>à</del>								

		X CURRENTE PERSON OF WATER SHIP OF
	O DRILLO CHANGE PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF.
-	TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
	O RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION T	TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT JEU 16 1959
NOTICE OF INTENTION T	O PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORYU 3 GEOLOGICAL SUP
NOTICE OF INTENTION T	TO ABANDON WELL	FASSINGTON, NEW ME
	(INDICATE ABOVE BY CHECK MARK	C NATURE OF REPORT, NOTICE, OR OTHER DATA)
	(	
		<u>December 15</u> , 19 58
Hammond		(F.) v
'ell No	is located 790 ft. from	1. S line and 1850 ft. from   line of sec. 25
SE 🗓 25	27N	8W MMPM
		(Range) (Meridian)
o. Blanco-PC		New Mexico or Subdivision) (State or Territory)
	ing points, and all o	ses, weights, and lengths of proposed casings; indicate mudding jobs, comportant proposed work)
		·
		·
		d drill to the Pictured Cliffs  Surface casing, cement to surface  18 195
T S a	o commence at once and et approx 100 8 5/8 and test.	d drill to the Pictured Cliffs  surface casing, cement to surface  surface casing, cement to surface casi
T S a D w	o commence at once and et approx 100° 8 5/8 and test.	d drill to the Pictured Cliffs  Surface casing, cement to surface  Surface casing, cem
T S a D W	o commence at once and et approx 100 8 5/8 and test.  Trill to approx 2200 rith 125 sacks, and test erforate, fracture and	d drill to the Pictured Cliffs  surface casing, cement to surface  run logs, set 51 on Bottom, cement  st  d complete
T S a D W P	o commence at once and et approx 100' 8 5/8 s and test.  Till to approx 2200' n ith 125 sacks, and test erforate, fracture and plan of work must receive approval in	d drill to the Pictured Cliffs  Surface casing, cement to surface  Surface casing, cement to surface  Survey before operations may be commenced.
T S a D W P I understand that this	o commence at once and et approx 100' 8 5/8 s and test.  Till to approx 2200' n ith 125 sacks, and test erforate, fracture and plan of work must receive approval in	d drill to the Pictured Cliffs  Surface casing, cement to surface  Surface casing, cement to surface  Survey before operations may be commenced.
T S a D W P	o commence at once and et approx 100' 8 5/8 s and test.  Till to approx 2200' n ith 125 sacks, and test erforate, fracture and plan of work must receive approval in	d drill to the Pictured Cliffs  Surface casing, cement to surface  Surface casing, cement to surface  Survey before operations may be commenced.
T S a D W P I understand that this	o commence at once and et approx 100' 8 5/8 s and test.  Till to approx 2200' n ith 125 sacks, and test erforate, fracture and plan of work must receive approval in	d drill to the Pictured Cliffs  surface casing, cement to surface  run logs, set 51 on Bottom, cement  st  d complete

## NEW MEXICO OIL CONSERVATION COMMISSION

## Well Location and Acreage Dedication Plat

ection A.										1958	
perator John A	Raen				Lease	Hammond					
11 No	_ Unit Letter_	0	Section	n	25	Townsh	ip 27	North	Range§	West	NMPN
cated 700						Feet	From_	East	<u> </u>	· ·	Line
unty San Juan	G. L.	<b>Elev</b> a	tion _	5978		_ Dedicated A					Acres
me of Producing											
<del>-</del>	ator the only o	wner*	in the	dedi	cated a	reage outlin	ed on	the pla	at below	?	
	No	•									
	er to question o										ted
-	ization agreem nsolidation	ent or	otner	W150?	168	NO	<u>. 11</u>	answer	is "yes,	, -	
	er to question t	wois	*no. *	list	all the	owners and th	neir r	espect	ive inte	rests	below
	•••••		,								
	Owner					OFILE IS	and D	escript	ion		
	Owner				Of	FIVE	<u> </u>	OSCITPO	1011		
					/ KL	OLIAED /			_		<b>n</b>
•					T 55	24.0		D	FCE	IAE	<del></del>
					T DE	C 1 8 1958		1,			
					OIL	CON. COM.			ECE	6 1958	
						DIST. 3				<del>(* 1: 3)</del>	<del>  (   E   -</del>
ection. B								<b>U</b> . ~	ULUG	NEW I	NEXICO
	İ	1			1		l	FARR	LULOG INGTON.	MEAR	
					1		1		to cert		
					1				tion in		
					1		l .		s true a		
		1			1				est of my		
		l			1		а	nd beli	ef.		
					ţ			ď			
		- +			<del></del>		_	N olms	a. Eg	المسه	
					i	!			(Opera	tor)	
					i i						
					J I		-	(R	epresent	tative	<u> </u>
					l i			(**	op. 000m		,
					 		Box	1208	armingt	on Ne	w Mexci
		2 5			-				Addre	•	
								•			
	<b> </b> 	1			ļ		•		to cert	A. Ine	t the
	! !	1			ļ		-	rell loc			
	ł 1	1			!		_	olat in		r sas y	
	!	1			ļ		-	rom fie	era dore	365 10	turi
	1	1			1						
	<u> </u>	1			ļ.			ame is	tra on	200	
	<del> </del>				-+-			he best			an
	1				1			elief.		10000000000	57
	! [	1		<b>∞</b> ∕	1 4	250' ·			rveyed De	ec,15,	1958
	1				1	350'	1	_		- / <	1
	, 	į į		o'	i		<b>.</b>	ance	1/4.C	aro	hou
	1			6	1		•		V. Echoh		
	1	J			Į		F	Registe	red Lan	d Surv	eyor.
	<del></del>					والمرابعة			cate No		
		_									