Form 3180-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTIC	ES AND REPORTS ON WELLS	5. Lease Designation and Serial No.
Do not use this form for proposals	2: Ø5SF-077951-A	
	N FOR PERMIT - " for such proposals	6. If Indian, Allottee or Tribe Name
	O70 FARMINGTON	i NM
	V) V (1 11 11 11 11 1 1 1 1 1 1 1 1 1 1 1	7. If Unit or CA, Agreement Designation
1. Type of Welt		
Well Well Other		8. Well Name and No.
2. Name of Operator Amoco Production Company	Attention:	Jack Frost B #1
3. Address and Telephone No.	Pat Archuleta, Room 1205C	
P.O. Box 800, Denver, Colorado 80	201 (303) 830-5217	3004506222 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Surve	y Description)	Gallup/Basin Dakota
1190'FSL 895'FEL	Sec. 27 T 27N R 10W Unit P	Con luna No. 14
CHECK ADDODDIATE	7 707/17 70 14/2017	San Juan New Mexico
1	BOX(s) TO INDICATE NATURE OF NOTICE	E , REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	ION
İ	Π	
Notice of Intent	Abendonment Recompletion	Change of Plans New Construction
	Plugging Back	Non-Routine Fracturing
L_J Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Aftering Casing Other	Conversion to Injection Dispose Water
	[Not	e: Report results of multiple completion on Well Completion or propletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly	state all pertinent details, and give pertinent dates, including estimated date of	
subsurface locations and measured and true vertical	depths for all markers and zones pertinent to this work.)*	
Amoco Production Company requ	est permission to downhole commingle this well per	the attached procedures.
If you have any technical question	ns contact Steve Webb at (3003) 830-4206.	
,		the second of th
		The second
We received written approval on (06/17/96, re- NMOCD order No. DHC-1273.	
The reserves written approval on t	50/17/50, Te- MMOCD (Idel No. DHC-1273.	IAN 2.7
		JAN 2 7 1997
		600
		OIL COM. DIV.
		DIST. 3
		en e
14. I hereby certify that the poregoing is true and sorrect	1	
signed to Grehule	Title Staff A	Assictant 01-13-1996
	Title Storr,	APPROVED
(This space for Federal or State office use)		
Approved by	Title	IAN 9 2 1997
Conditions of approval, if any:	Title	JANo 23 1997 /S/ Duane W. Spencer
Title 18 U.S.C. Section 1001, makes it a crime for any perepresentations as to any matter within its jurisdiction.	erson knowingly and willfully to make to any department or agency of the Unite	d States any false, Spicial ANGER
	NMOCD	, , ,
DHC-1273 (5)	* See Instructions on Reverse Side	
		AND THE RESIDENCE AND ADDRESS OF THE PARTY O



Jack Frost B #1
Orig. Comp. 3/59
TD = 6955' PBTD = 6940'
GL = 6534', KB = 6544'
Page 2 of 2

- Check location for anchors. Install if necessary. Test anchors. Record shut-in casing, tubing, and bradenhead pressures.
- 2. MIRUSU. Blow down well. Kill if necessary with 2% KCL.
- 3. POOH with 2 3/8" short string and rods. TOOH w/ 2 3/8" long string. Uncertain if packer is retrievable or permanent.
- 4. If permanent packer, TIH w/ tbg x "metal muncher" mill. Mill out packer. Clean out to PBTD. TOOH w/ tbg.
- 5. .TIH w/ 2 3/8" tbg (1/2 mule shoe on bottom w/ seating nipple one joint up). Land tubing at 6825-350'. Flow or swab well to clean up. ND BOP. NU wellhead. RDSU x move off.
- 6. Flow well to clean-up. Swab if necessary. Record and report flow test results. Turn well over to production.

Contact for questions:

Steve Webb (303)830-4206

Amoco	Production	Company
-------	------------	---------

ENGINEERING CHART


RECEIVED

TACK FLOST BI SUBJECT.

97 JAN 17 PH 2: 05

BY GWK

 $^{1.5}$ 070 Farmington, NM



GP & 6161-87

ent w/625 sxs cut

