



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office

Lease No. **SF-079114-A**

Unit

**Campbell Federal**

## SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	OCT 17 1962
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	U.S. GEOLOGICAL SURVEY
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	FARMINGTON, NEW MEXICO
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 16, 1962

Well No. 4 is located 1450 ft. from S line and 1450 ft. from W line of sec. 25  
NE/4 SW/4 Sec. 25 27 N 12 W 100PM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Basin Dakota San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6001 ft. G.L.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10/6/62 Rigged up pulling unit. Ran 35 jts. 2" tbg. 10/7/62 Ran 100 jts. tbg.  
10/9/62 Tagged bottom @ 6103'. Squeezed 15 ex cement in perfs. 6062-97, left 220' cement  
plug in casing above perfs. Top cement approx. 5842'. 10/10/62 Layed 2" tbg. down.  
Shot casing @ 4961'. Could not circulate or move casing. 10/11/62 Shot casing @ 4791'.  
Worked loose. Pulled 7 jts. could not circulate. 10/12/62 Pulled 38 jts. casing.  
Still not free. 10/13/62 Recovered total of 150 jts. 5 1/2" 15.50# casing. 10/14/62 Ran  
2" tbg. Set 40 ex. cement plug 4820-4787 (29' inside casing stub) and 60 ex cement  
plug 1183-1060. Pulled tbg. set marker and 30' cement plug at surface. Well plugged  
and abandoned. 10/13/62.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southwest Production CompanyAddress 207 Petr. Club PlazaFarmington, New MexicoOriginal signed by  
Carl W. Smith

By

Title Superintendent