

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SF-078896

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> WELL WELL		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Beta Development Co.		8. FARM OR LEASE NAME Mudge Federal	
3. ADDRESS OF OPERATOR 125 Petroleum Plaza Farmington, N.M. 87401		9. WELL NO. 3	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface NE/4 SW/4 1850/S 1850/W		10. FIELD AND POOL, OR WILDCAT Basin Dakota	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29 27N-11W RMPM	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6184.5' G.L.		12. COUNTY OR PARISH San Juan	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rig up, pull 1 1/2" tubing, lay down 1 jt. with holes, rerun tubing mix and spot 50 sacks cement to 6350' close valve on head and squeeze cement into perforations 6355-77' pick tubing up to 6100' mix and spot 25 sacks cement, pick tubing up to 4300' mix and spot 20 sacks cement, pick tubing up to 2600' mix and spot 25 sacks cement, pull tubing up hole to 2-stage collar @ 1953' mix and spot 25 sacks cement, lay all 1 1/2" tubing down, shoot 4 1/2" casing into @ 771' lay 25 jts. down, run 1 1/2" tubing in hole to 881' 100' inside casing stub mix and spot 35 sacks cement, pull tubing up hole to 260' mix and spot 25 sacks cement, mix and pump 10 sacks in top of surface, no dry hole marker required, agricultural area.

NEW MEXICO RECLAMATION COMA
1000 MC CANALS REL
AZTEC, NEW MEXICO STATE

18. I hereby certify that the foregoing is true and correct

SIGNED D. E. Bayler TITLE Superintendent DATE 3-10-78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side