

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-B for such proposals.)

1. oil ☐ gas ☒ other ☐
well well
2. NAME OF OPERATOR
Beta Development Company
3. ADDRESS OF OPERATOR
125 Petroleum Plaza Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: NE 1/4 NW 1/4 790/N-1850/W
AT TOP PROD. INTERVAL: 6550
AT TOTAL DEPTH: 6675

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE
SF-078092
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Douthitt Federal
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 27 27N-11W NMNM
12. COUNTY OR PARISH
San Juan
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6370' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug and abandon the above mentioned well in the following manner subject to your approval:

- #1 Pump 50 sacks cement into Dakota perforations 6550-6634.
- #2 Pump 25 sacks cement on top of perforations 6550-6273
- #3 Pump 25 sacks cement across 2 stage collar @ 2193-1921 across P. O.
- #4 Shoot and recover any free 4 1/2" casing.
- #5 Pump cement plug 50' in and 150' out of casing stub.
- #6 Pump cement plug from 950'-1150' (base of Ojo-Alamo @1015')
- #7 Cut all pipe off 4' below ground level, (Agricultural area) no dry hole marker required.
- #8 Pump 10 sacks cement in top of 10 3/4" surface pipe.
- #9 Clean up location and rehabilitate in accordance of B.L.M. instructions.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED D. E. Burt TITLE Superintendent DATE March 19, 1980

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED

MAR 21 1980
James F. Sims
JAMES F. SIMS
DISTRICT OIL & GAS SUPERVISOR