




LOCATE WELL CORRECTLY

UNITED STATES

11/18/72

[illegible]

Journal of Management Inquiry 18(6)br/>DOI: 10.1177/1056492609352811
© The Author(s) 2009

Two sacks of second grade pipe was clear to 2184' with a 4" hole. Cement was poured and casing perforated (water - 4 shots per ft) from 2110' to 2160'. Peris worked with and traced with 1000 parts water and 30,000 sand. Well shut in awaiting pipeline connection.

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any, "sidetracked," or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and results of pumping of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping.

16-43094-2 U. S. GOVERNMENT PRINTING OFFICE

STANLEY

FORMATION RECORD-Continued