Form 3160-5

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

UNITED STATES	/	FORM APPROVED
ARTMENT OF THE INTERIOR EAU OF LAND MANAGEMENT		Budget Bureay No. 1004-01; Expires: March 31, 1993


DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals		Budget Bureau No. 1004-0135 Expires: March 31, 1993	
		5. Lease Designation and Serial No. NM-103380 6. If Indian, Allottee or Tribe Name	
		7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Gas Well Well Other		8. Well Name and No.	
2. Name of Operator	Attention:	Florance D LS #4	
Amoco Production Company		9. API Well No.	
3. Address and Telephone No.	Bobbe Bien Cancy	2004506276	
P.O. Box 800, Denver, Colorad	do 80201	3004506376	
4. Location of Well (Footage, Sec., T., R., M., o	Blanco Mesaverde Prt Cou		
1840'fnl 1800'fe	el Sec. 20 T 27N R 🕏 W Unit G	77. County of 7 anality, State	
	•	San Juan New Mexico	
12. CHECK APPROPE	RIATE BOX(s) TO INDICATE NATURE OF NOTICE	REPORT OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTIO		
TITE OF SUBMISSION	TIPE OF ACTIO	N .	
Notice of Intent Subsequent Report Final Abandonment Notice		Change of Plans New Construction Non-Routine Fracturing Water Shur-Off Conversior to Injection Dispose Water Report results of multiple completion on Well Completion or election Report and Log form.	
	s (Clearly state all pertinent details, and give pertinent dates, including estimated date of sta	rting any proposed work . If well is directionally drilled, give	
	we vertical depths for all markers and zones pertinent to this work.)* • abandon the subject location per the attached procedure.		
	Oil C	94. 1994 97. FEB 28 FH 1: 25 ON. DIV. ST. S	

14.1 hereby certify that the foregoing is true and correct Signed A. Babbe Bren-Carley	Title	Business Analyst	Date 02-21-1994
(This space for Federal or State office use) Approved by	Title		APPROVED
Conditions of approval, if any:			- MAR 04 1994
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully representations as to any matter within its jurisdiction.	to make to any department	or agency of the United States any faise, fider	HOTOIR NATIONALED

PXA Procedures Florance D LS #4

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water.
- 3. POOH with 1 1/4" tbg. RIH with tbg and cement retainer. Set retainer at 2590'. Test casing integrity to 500#. Squeeze perfs at 2644' to 2753' with 119.025 cuft cement. Pull out of retainer and spot cement plug to 850' with cuft cement. (593.253 cuft cement)
- 4. RIH with perf gun and shoot squeeze holes at 800. RIH with cement retainer, set retainer at 50' above squeeze holes and attempt to circulate to surface with 274.57 cuft cement. Pull out of retainer and fill hole to surface with 255.713 cuft cement.
- 5. NDBOPE. Cut off casing and wellhead. Install PXA maker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

FLORANCE D LS 004 Location — 20G—27N—8W SINGLE mv Orig.Completion — 2/56 LAST FILE UPDATE — 2/94 BY CSW



5 1/2 CASING CUT AND PULLED @2875

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 La Plata Highway Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 4 Florance DLS

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Weils on Federal and Indian Leases."
- 2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made (when applicable):
- 1.) Spot a cement plug from 2843' (PBTD') to 2753' (61m put).

 (PC TOP 2795')
- 2.) If cement is Not circulated to the surface from 800', perforate 2224' and circulate cement to the surface.

Office Hours: 7:45 a.m. to 4:30 p.m.