

**OIL CONSERVATION COMMISSION**  
1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO

*October 17, 1962*

*Mr. D. B. Morrison  
The Frontier Refining Co.  
4040 East Louisiana Ave.  
Denver 22, Colorado*

*Re: Government Evensen #3 "G"  
G-19-27N-10W, Angels Peak  
Gallup Oil Pool*

*Dear Mr. Morrison:*

*A gas-oil ratio test is required each January, April, July and October for each well completed in subject pool by the special pool rules. Such test is not required until all load oil is recovered from any particular well.*

*Copy of the pool rules is enclosed for your convenience.*

*Yours very truly*

*A. R. Kendrick  
Engineer, District #3*

**ABK:ks**

**Encl.**

WILSON COUNTY CONSERVATION COMMISSION  
1000 RFD BRIDGE ROAD  
MOUNTAIN VIEW, TEXAS 75755

Dear Sirs:

Enclosed for you are two copies of the Wilson County Conservation Commission's report on the proposed development of the Wilson County Conservation Commission's property.

Very truly yours,  
Wilson County Conservation Commission  
Enclosure

Very truly yours,

Enclosed for you are two copies of the Wilson County Conservation Commission's report on the proposed development of the Wilson County Conservation Commission's property. The report is dated 10/1/75 and is a copy of the report of the Wilson County Conservation Commission's property.

Very truly yours,

Wilson County Conservation Commission

Wilson County Conservation Commission  
Enclosure

Very truly yours,

Wilson County Conservation Commission



# THE FRONTIER REFINING COMPANY


4040 EAST LOUISIANA AVENUE • DENVER 22, COLORADO • Skyline 6-1511

October 12, 1962

New Mexico Oil Conservation Commission  
1000 Rio Brazos Road  
Aztec, New Mexico

Attention: Mr. A. R. Kendrick

Re: The Frontier Refining Company  
Government Evensen No. 3-G  
Located: Unit G, 19-27N-10W  
San Juan County, New Mexico  
(Angels Peak Gallup Pool)  
SF 078004



Dear Sir:

Subject well was completed in August, 1961, and has not yet been assigned an allowable because all load oil used for completion has not yet been recovered. The attached summaries of load oil recovered and sold are intended to inform you of the present status of production and load oil recovery.

Also enclosed are two copies of the results of a GOR test of subject well taken June 6, 1962 and filed with the Commission June 26, 1962. El Paso Natural Gas Company has informed our pumper in Farmington that they will accept no more gas from this well until a gas-oil ratio test has been filed with you. Please advise us if additional GOR tests should be taken at this time; this well has not yet recovered all load oil, and your letter of July 13, 1962 advises that we should file a corrected Form C-104 showing potential after recovery of load oil. Your office of course cannot assign an allowable to this well until the above-mentioned form has been filed.

One last request. Please advise us when the next GOR tests are to be taken in this pool. If you require any additional information, please advise us at your convenience.

Yours very truly,

THE FRONTIER REFINING COMPANY

D. Morrison  
Petroleum Engineer

DBM:dm

cc: El Paso Natural Gas Co.  
Farmington, New Mexico  
Attn: Mr. E. E. Alsup