

AMERADA HESS CORPORATION

P. O. DRAWER D
MONUMENT, NM 88265

September 10, 2001

State of New Mexico
Oil Conservation Division
1000 West Broadway
Hobbs, NM 88240



Re: Summary of MIT compliance work for TA'd and shut-in wells

Attn: Mr. Chris Williams, District 1 (Hobbs) Supervisor
Mr. Roy Johnson, District 4 (Santa Fe) Supervisor
Mr. Frank Chavez, District 3 (Aztec) Supervisor
Ms. Lori Wrotenbery, Director, NMOCD

Dear NMOCD Supervisors and Director,

Amerada Hess Corporation is nearing completion of regulatory MIT work on various TA'd and shut-in wells as required by the NMOCD in its notification memo dated May 11, 2000, and also discussed in AHC's response letter dated February 23, 2001. AHC's response letter proposed a six month window in which to bring all referenced wells into compliance. To that end AHC has worked diligently to meet that deadline and files this update of our progress.

Hobbs District 1 – Monument Area General

NMGSAU

58 wells on NMOCD notification lists

54 wells brought into regulatory compliance -

8 wells re-activated to production

46 wells under approved TA or SI status

4 wells out of compliance -

NMG2209 - failed repair attempt. Eval. f/ P&A or repair (1/1/02).

NMG2305 – site access temporarily denied. Planned recompletion f/ 4th quarter 2001.

NMG604 – evaluating re-activation attempt. Planned for 3rd quarter 2001.

NMG808 – site access denied by surface owner. See letters to District 1 supervisor.

Monument Area other than NMGSAU

45 wells on NMOCD notification lists

35 wells brought into regulatory compliance -

2 wells re-activated to production

33 wells under approved TA or SI status

10 wells out of compliance -

F. Turner A#3 – Recompletion candidate awaiting surface access issues (1/1/02).

F. Turner C#1 – Recompletion candidate awaiting surface access issues (1/1/02).

B. Barber#3 – Set CIBP and perform MIT (11/1/01)

B. Barber#5 – Repair leak and perform MIT (11/1/01)

J. R. Phillips#7 - Repair leak and perform MIT (11/15/01)

J. W. Cooper F#4 - Repair leak and perform MIT (11/15/01)

Hobbs District 1 (cont'd)

Wood State A#1 – Set CIBP and perform MIT (11/1/01)
Wood State A#2 - Set CIBP and perform MIT (11/1/01)
State O #4 – Pulled parted casing. Eval. repair or P&A (11/01).
WMU#114 – Squeeze casing leak and perform MIT (10/01).

Santa Fe District 4 – Monument Area / West Bravo Dome

West Bravo Dome

25 wells on NMOCD notification lists

20 wells brought into regulatory compliance -

20 wells under approved TA or SI status

5 wells out of compliance -

WBDU01 - failed MIT. Evaluating f/ repair.

WBDU13 - failed MIT. Evaluating f/ repair.

Mitchell#6 – No test due to wellhead valves not operating. Repair and retest(11/01).

Mitchell#12 – failed MIT. 12 bbls to load annulus. Evaluate f/ repair.

Mitchell#19 – failed MIT. Wellhead packing leaking. Repair wellhead and retest(11/01)


Santa Fe District 3 – Monument Area / Navajo lands

1 well on NMOCD notification lists

1 well is not the property of AHC – Frank Chavez has been supplied documentation of the assumption of operatorship by the Bureau of Indian Affairs. AHC has email indicating Mr. Chavez is awaiting verification from the BIA.

AHC continues its effort to meet all state regulatory requirements. To date AHC has addressed and corrected regulatory issues on 110 of 129 wells. We continue to actively address issues on the remaining 19 wells where repair or site access issues are being addressed. Please call or email with corrections or concerns. AHC appreciates your patience in this matter.

Sincerely,



Rob Williams
Sr. Production Foreman
Amerada Hess Corporation / Monument Area

Attachments:

- 1) AHC spreadsheet summarizing Hobbs District 1 SI and TA'd wells ('NMOCD NON-COMPLIANCE 012301.xls')
- 2) NMOCD spreadsheet originally authored by Lori Wrotenbery and edited/updated by Rob Williams/AHC ('Amerada Spreadsheet010416.xls') for all Districts 1, 3, 4.

Inactive Wells

4/16/2001

API #	District	Type / Injection	Last Production	Well Name and Number	NMG Well No.	OGRI	Operator	ULSTR	OCDD Unit Letter	FNS	F&W	Depth	Surface Owner	Federal Minerals	Proposed Action/Date and Comments	Date Resolved	Blanket Bond	Single Well Status
30-025-05973	HOBBES	O	11-1998	BERTHA J BARBER #001	1	495	AMERADA HES H-07-20S-37E	H	2310N	990E	3821	P	P		Pull A/L, set CIBP 3377, MIT	6/15/01	50000	A
30-025-05974	HOBBES	O	NONE	BERTHA J BARBER #002	2	495	AMERADA HES A-07-20S-37E	A	330N	990E	3894	P	P		MIT/passed	2/6/01	50000	T
30-025-06020	HOBBES	O	02-1987	BERTHA J BARBER #003	3	495	AMERADA HES L-08-20S-37E	L	2310S	990W	3864	P	P		Repair and retest	11/1/01	50000	A
30-025-06021	HOBBES	O	NONE	BERTHA J BARBER #004	4	495	AMERADA HES D-08-20S-37E	D	330N	990W	3900	P	P		MIT/passed	2/6/01	50000	T
30-025-05975	HOBBES	O	NONE	BERTHA J BARBER #005	5	495	AMERADA HES P-07-20S-37E	P	330S	330E	3900	P	P		Repair and retest	11/1/01	50000	T
30-025-05901	HOBBES	O	06-1985	E S ADKINS #001	1	495	AMERADA HES M-05-20S-37E	M	660S	660W	3909	P	P		MIT/passed	2/6/01	50000	T
30-025-07808	HOBBES	O	05-1986	FRED TURNER JR A #001	1	495	AMERADA HES A-19-20S-38E	A	990N	990E	3915	P	P		Repaired wellhead. MIT/passed	7/17/01	50000	A
30-025-07787	HOBBES	O	10-1990	FRED TURNER JR A #004	4	495	AMERADA HES F-18-20S-38E	F	1980N	1987W	3915	P	P		Pull A/L, CIBP 2860, MIT/pass	6/28/01	50000	T
30-025-04136	HOBBES	O	11-1988	J R PHILLIPS #007	7	495	AMERADA HES H-01-20S-36E	H	1980N	760E	10214	F	F		Repair IP 6/20/01		50000	A
30-025-05931	HOBBES	O	12-1992	L M LAMBERT #007	7	495	AMERADA HES I-06-20S-37E	A	990N	660E	660E	P	P		MIT/passed	2/6/01	50000	T
30-021-05071	SANTA F	G	05-1992	MITCHELL #006	6	495	AMERADA HES M-08-19N-30E	M	999S	999E	999E	P	P		Bad valves. Could not test	11/1/01	50000	O
30-021-05091	SANTA F	G	03-1994	MITCHELL #012	12	495	AMERADA HES F-20-19N-30E	F	999S	999E	999E	P	P		22 bbls to load. Valves leaked	11/1/01	50000	O
30-021-20044	SANTA F	C	09-1990	MITCHELL #019	19	495	AMERADA HES E-04-18N-30E	E	999S	999E	999E	P	P		Wellhead packing leaked	11/1/01	50000	O
30-025-05929	HOBBES	O	NONE	MONUMENT G/SA UT. BLK 20 N #007	2007	495	AMERADA HES G-06-20S-37E	G	2314N	2310E	5710	F	F		MIT/passed	1/31/01	50000	O
30-025-05882	HOBBES	O	12-1992	MONUMENT G/SA UNIT #001	1701	495	AMERADA HES C-20-27N-37W	C	660N	1980W	7895	N	N		Assigned to Nevada 6/7/78 see attached assignment.	6/7/78	50000	A
30-025-05870	HOBBES	O	02-1996	NORTH MONUMENT G/SA UNIT #002	2302	495	AMERADA HES A-33-19S-37E	A	330N	330E	4153	P	P		Set CIBP 3668, MIT/passed	8/8/01	50000	O
30-025-09891	HOBBES	O	12-1992	NORTH MONUMENT G/SA UNIT #003	2202	495	AMERADA HES B-03-20S-37E	B	330N	1648E	3846	P	P		MIT/passed	6/28/01	50000	O
30-025-26608	HOBBES	O	03-1992	NORTH MONUMENT G/SA UNIT #004	1703	495	AMERADA HES D-04-20S-37E	D	760N	1780W	3950	F	F		repair csg. / MIT	7/22/01	50000	O
30-025-04122	HOBBES	O	03-1998	NORTH MONUMENT G/SA UNIT #005	1304	495	AMERADA HES C-35-19S-36E	C	660N	660W	3845	F	F		MIT/passed	1/31/01	50000	O
30-025-05668	HOBBES	O	05-1984	NORTH MONUMENT G/SA UNIT #006	1804	495	AMERADA HES D-35-19S-36E	D	660N	660W	3930	P	P		Pull A/L, set CIBP 3748, MIT	5/4/01	50000	O
30-025-05881	HOBBES	O	03-1994	NORTH MONUMENT G/SA UNIT #007	604	495	AMERADA HES E-02-20S-36E	E	660N	660W	3973	S	S		MIT/passed	1/31/01	50000	O
30-025-05882	HOBBES	O	10-1995	NORTH MONUMENT G/SA UNIT #008	2304	495	AMERADA HES D-20-19S-37E	D	660N	660W	3900	P	P		Evaluating reactivation	11/1/01	50000	O
30-025-05871	HOBBES	O	03-1995	NORTH MONUMENT G/SA UNIT #009	2305	495	AMERADA HES E-03-20S-37E	E	813N	330W	3900	P	P		Evaluating reactivation	6/26/01	50000	O
30-025-05899	HOBBES	G	09-1991	NORTH MONUMENT G/SA UNIT #010	2306	495	AMERADA HES F-03-20S-37E	F	1650N	330W	6750	P	P		Repair and retest	11/15/01	50000	O
30-025-05912	HOBBES	O	06-1976	NORTH MONUMENT G/SA UNIT #011	2106	495	AMERADA HES G-03-20S-37E	G	1980N	1980W	3938	P	P		Evaluating reactivation	1/1/02	50000	O
30-025-05872	HOBBES	G	05-1995	NORTH MONUMENT G/SA UNIT #012	2307	495	AMERADA HES F-04-20S-37E	F	1980N	1980W	3900	P	P		Evaluating reactivation	1/31/01	50000	O
30-025-04080	HOBBES	O	12-1992	NORTH MONUMENT G/SA UNIT #013	808	495	AMERADA HES G-05-20S-37E	G	1676N	1977E	4004	P	P		Set CIBP 3300, MIT/passed	5/18/01	50000	O
30-025-05625	HOBBES	O	01-1995	NORTH MONUMENT G/SA UNIT #014	208	495	AMERADA HES H-06-20S-37E	H	1980N	1980W	4004	P	P		Repaired wellhead. MIT/passed.	8/8/01	50000	O
30-025-05894	HOBBES	G	02-1992	NORTH MONUMENT G/SA UNIT #015	2208	495	AMERADA HES I-07-19S-37E	I	1980N	660E	4026	P	P		Repaired wellhead. MIT/passed	6/28/01	50000	O
30-025-05568	HOBBES	O	12-1984	NORTH MONUMENT G/SA UNIT #016	109	495	AMERADA HES J-26-19S-36E	J	1980N	660E	4046	S	S		Surface owner denies access-NMOCD(Hobbs notified)	1/1/02	50000	O
30-025-05801	HOBBES	O	02-1992	NORTH MONUMENT G/SA UNIT #017	2209	495	AMERADA HES K-18-19S-37E	K	1650N	660E	4046	P	P		Reactivated	4/15/01	50000	O
30-025-05895	HOBBES	O	07-1995	NORTH MONUMENT G/SA UNIT #018	2209	495	AMERADA HES L-18-19S-37E	L	1650N	660E	4046	P	P		Set CIBP 3300, MIT/passed	5/18/01	50000	O
30-025-04050	HOBBES	O	03-1992	NORTH MONUMENT G/SA UNIT #019	411	495	AMERADA HES M-04-20S-37E	M	2084N	660E	4046	P	P		Pull A/L, set CIBP 3500, MIT	5/22/01	50000	O
30-025-04079	HOBBES	O	04-1992	NORTH MONUMENT G/SA UNIT #020	811	495	AMERADA HES N-04-20S-37E	N	1980S	660E	4046	P	P		Pull A/L, set CIBP 3650, MIT	5/14/01	50000	O
30-025-05900	HOBBES	O	04-1982	NORTH MONUMENT G/SA UNIT #021	2211	495	AMERADA HES O-04-20S-37E	O	1980S	1980W	4005	S	S		Pull A/L, set CIBP 3650, MIT	5/14/01	50000	O
30-025-04057	HOBBES	G	05-1990	NORTH MONUMENT G/SA UNIT #022	912	495	AMERADA HES P-25-19S-36E	P	1980S	660W	4001	P	P		Pull A/L, set CIBP 3650, MIT failed	1/1/02	50000	O
30-025-05772	HOBBES	O	07-1992	NORTH MONUMENT G/SA UNIT #023	1513	495	AMERADA HES Q-31-19S-37E	Q	660S	660W	5709	P	P		Set CIBP 3700, MIT/passed	5/9/01	50000	O
															Repaired wellhead. MIT/passed	8/8/01	50000	O
															Cmt. Sq 3622 liner top. Spot Sq. 1343. MIT/passed	7/17/01	50000	O
															Repaired wellhead flange. Performed MIT/passed	8/7/01	50000	O
															MIT/passed	4/24/01	50000	O

Inactive Wells

API #	District	Last Production Type / Injection	Well Name and Number	NMGC Well No.	OGRI	Operator	ULSTR	OCU Unit Letter	FNS	FEW	Depth	Surface Owner	Federal Minerals	Proposed Action/Date and Comments	Date Resolved	Blanket Bond	Single Well Bond	Status
30-025-05798	HOBBES	O 02-1992	NORTH MONUMENT G/SA UNIT #013	1713	D 495	AMERADA	HE'S M-33-19S-37E	M	660S	660W	3910	P		Pull A/L, set CIBP 3530, MIT	5/16/01	50000	0	A
30-025-05889	HOBBES	O 06-1995	NORTH MONUMENT G/SA UNIT #013	2213	D 495	AMERADA	HE'S M-04-20S-37E	M	660S	660W	3890	P		MIT/passed	1/31/01	50000	0	T
30-025-20226	HOBBES	O 06-1994	NORTH MONUMENT G/SA UNIT #013	313	D 495	AMERADA	HE'S M-17-19S-37E	M	330S	330W	4006	S		not NMGS/AV, CIBP 3530, MIT/passed	7/27/94	50000	0	A
30-025-05574	HOBBES	O 03-1992	NORTH MONUMENT G/SA UNIT #014	114	D 495	AMERADA	HE'S N-07-19S-37E	N	330S	2310W	4018	P		Sq.cmt leak 490. MIT/passed	5/10/01	50000	0	A
30-025-05799	HOBBES	O 12-1991	NORTH MONUMENT G/SA UNIT #014	1714	D 495	AMERADA	HE'S N-33-19S-37E	N	330S	2310W	3910	P		CIBP 3412, sq.cmt. 2030, MIT	5/14/01	50000	0	A
30-025-05890	HOBBES	O 11-1993	NORTH MONUMENT G/SA UNIT #014	2214	D 495	AMERADA	HE'S N-04-20S-37E	N	660S	1980W		P		Sq.cmt 1974-2006, MIT/pass	6/8/01	50000	0	A
30-025-05616	HOBBES	O 02-1998	NORTH MONUMENT G/SA UNIT #015	315	D 495	AMERADA	HE'S O-17-19S-37E	O	660S	1980E	3995	S		Set CIBP@3710, MIT/passed	8/7/01	50000	0	S
30-025-05817	HOBBES	O 11-1995	NORTH MONUMENT G/SA UNIT #015	2315	D 495	AMERADA	HE'S O-34-19S-37E	O	330S	1980E	3578	P		MIT/passed	1/31/01	50000	0	T
30-025-05811	HOBBES	O 01-1994	NORTH MONUMENT G/SA UNIT #016	2215	D 495	AMERADA	HE'S O-04-20S-37E	O	660S	1980E		P		Sq.cmt. 1386/ MIT/passed	6/13/01	50000	0	T
30-025-05618	HOBBES	O 05-1995	NORTH MONUMENT G/SA UNIT #016	1716	D 495	AMERADA	HE'S P-17-19S-37E	P	660S	990E	3995	S		Reactivated	5/15/01	50000	0	A
30-025-05812	HOBBES	O 05-1995	NORTH MONUMENT G/SA UNIT #016	1716	D 495	AMERADA	HE'S P-33-19S-37E	P	330S	840E	3923	P		Reactivated	4/15/01	50000	0	A
30-025-05814	HOBBES	O 04-1995	NORTH MONUMENT G/SA UNIT #016	2316	D 495	AMERADA	HE'S P-34-19S-37E	P	330S	988E	4000	P		Pull A/L, set CIBP 3650, MIT	6/21/01	50000	0	T
30-025-05896	HOBBES	G 12-1993	NORTH MONUMENT G/SA UNIT #016	2216	D 495	AMERADA	HE'S P-04-20S-37E	P	660S	660E	3912	P		Pull A/L, set CIBP 3612, MIT	6/15/01	50000	0	S
30-025-04174	HOBBES	O 03-1996	NORTH MONUMENT G/SA UNIT #017	1317	D 495	AMERADA	HE'S H-34-19S-36E	H	1980N	660E	3906	F		Pull A/L, set CIBP 3586, MIT	5/7/01	50000	0	A
30-025-04178	HOBBES	O 06-1991	NORTH MONUMENT G/SA UNIT #017	1817	D 495	AMERADA	HE'S I-03-20S-36E	A	660N	660E	9822	S		MIT/passed	1/31/01	50000	0	T
30-025-05961	HOBBES	O NONE	NORTH MONUMENT G/SA UNIT #032	1432	D 495	AMERADA	HE'S P-36-19S-36E	P	660S	660E	9822	S		Pull A/L, set CIBP 3324, MIT	4/27/01	50000	0	A
30-025-20517	HOBBES	G 07-1995	NORTH MONUMENT G/SA UNIT #283	2006	D 495	AMERADA	HE'S P-06-20S-37E	F	2310N	2261W	5730	P		Pull A/L, set CIBP 3400, MIT	4/22/01	50000	0	A
30-025-33618	HOBBES	O NONE	NORTH MONUMENT G/SA UNIT #286	1423	D 495	AMERADA	HE'S G-36-19S-36E	G	1980N	1830E	9900	S		MIT/passed	5/8/01	50000	0	T
30-025-04143	HOBBES	O NONE	NORTH MONUMENT G/SA UNIT #624	624	D 495	AMERADA	HE'S H-20-19S-37E	H	1830N	660E	5100	S		SI WSW. Capacity not req'd. Reactivate 7/02	8/8/01	50000	0	A
30-025-04146	HOBBES	O 03-1989	STATE D #005	5	D 495	AMERADA	HE'S J-01-20S-36E	J	766N	1874W	5220	S		Reactivated	3/16/01	50000	0	A
30-025-04247	HOBBES	O 02-1978	STATE H #002	2	D 495	AMERADA	HE'S J-13-20S-36E	J	1980S	1980E	3879	S		Set CIBP 3700, MIT/passed	5/17/01	50000	0	A
30-025-24822	HOBBES	O 03-1978	STATE M #002	2	D 495	AMERADA	HE'S J-13-20S-36E	J	1980S	1980E	3865	S		MIT/passed	2/6/01	50000	0	T
30-025-25108	HOBBES	O 01-1993	STATE Q #005	5	D 495	AMERADA	HE'S O-16-20S-37E	O	800S	1980E		S		MIT/passed	4/30/01	50000	0	A
30-025-26614	HOBBES	G 06-1998	STATE W #005	6	D 495	AMERADA	HE'S P-16-20S-37E	P	660S	660E		S		Reactivated	5/1/01	50000	0	S
30-025-06011	HOBBES	G 08-1997	STATE X #001	5	D 495	AMERADA	HE'S P-16-20S-37E	E	1980N	780W		S		Pull A/L, set CIBP3247, MIT	9/7/01	50000	0	A
30-025-07806	HOBBES	O 12-1992	STATE Y #001	1	D 495	AMERADA	HE'S L-16-20S-37E	L	1980S	660W	3783	S		MIT/passed	2/6/01	50000	0	T
30-025-07760	HOBBES	O 12-1992	T ANDERSON #001	1	D 495	AMERADA	HE'S L-16-20S-37E	K	1980S	1980W	9400	P		Pull A/L, set CIBP 2780, MIT	6/24/01	50000	0	A
30-025-07786	HOBBES	O 09-1997	WARREN MCKEE UNIT #101	101	D 495	AMERADA	HE'S B-18-20S-38E	B	990N	1650E	4072	P		MIT/passed	5/3/01	50000	0	A
30-025-07809	HOBBES	O 12-1983	WARREN MCKEE UNIT #102	102	D 495	AMERADA	HE'S K-08-20S-38E	L	1650S	330W	4072	P		Pull A/L, set CIBP 2780, MIT	10/22/02	50000	0	T
30-025-07792	HOBBES	O NONE	WARREN MCKEE UNIT #114	114	D 495	AMERADA	HE'S B-18-20S-38E	P	660S	660E	9200	P		MIT valid until 10/22/02	1/1/02	50000	0	A
30-025-07740	HOBBES	O 12-1992	WMU #113/F. Turner A #3	113	D 495	AMERADA	HE'S P-18-20S-38E	A	660N	660E	9325	P		Evaluating reactivation	10/1/01	50000	0	A
30-025-07741	HOBBES	O 12-1992	WARREN MCKEE UNIT #119	119	D 495	AMERADA	HE'S A-19-20S-38E	P	1980S	1880E	9240	F		repair csg./ MIT	8/8/01	50000	0	T
30-025-07742	HOBBES	O 12-1992	WARREN MCKEE UNIT #121	121	D 495	AMERADA	HE'S J-18-20S-38E	J	1980N	660W	9250	P		Sq.cmt. Evaluate reactivation	1/1/02	50000	0	A
30-025-07755	HOBBES	O 12-1992	WARREN MCKEE UNIT #201	201	D 495	AMERADA	HE'S E-17-20S-38E	E	3300N	660E	9220	P		MIT due 10/1/02	10/1/02	50000	0	T
30-025-07747	HOBBES	I NONE	WARREN MCKEE UNIT #202	202	D 495	AMERADA	HE'S I-07-20S-38E	I	1980S	1980E	0	P		MIT due 10/1/02	10/1/02	50000	0	T
30-025-07755	HOBBES	I NONE	WARREN MCKEE UNIT #203	203	D 495	AMERADA	HE'S K-07-20S-38E	K	1650S	2310W	9200	P		MIT due 10/1/02	10/1/02	50000	0	T
30-025-07747	HOBBES	O 12-1992	WARREN MCKEE UNIT #401	401	D 495	AMERADA	HE'S K-07-20S-38E	N	990S	330E	9367	P		CICR 5250, Circmt. MIT/pass	5/15/01	50000	0	T
30-021-20032	SANTA F	C NONE	WARREN MCKEE UNIT #601	601	D 495	AMERADA	HE'S P-07-20S-38E	P	660S	1980W	0	S		MIT/failed	1/25/01	50000	0	T
30-021-20120	SANTA F	C NONE	WEST BRAVO DOME UNIT #001	1	D 495	AMERADA	HE'S N-11-19N-29E	N	1980S	1980W	0	S		MIT/failed	1/1/02	50000	0	T
30-021-20140	SANTA F	C NONE	WBDO #001(?) (St. DN#1)	1	D 495	AMERADA	HE'S K-16-18N-30E	K	1980S	1980W	0	S		MIT/failed	8/8/01	50000	0	T
30-021-20140	SANTA F	C NONE	WBDO #001(?) (St. DS#1)	1	D 495	AMERADA	HE'S G-29-18N-30E	G	1980N	1980E	0	S		MIT/failed	8/8/01	50000	0	T

API #		District	Type	Production / Injection	Well Name and Number	NMG Well No.	OGRD	Operator	ULSTR	OCU Unit Letter	FNS	FEW	Depth	Surface Owner	Federal Minerals	Proposed Action/Date and Comments	Date Resolved	Blanket Bond	Single Well Bond	Status
30-021-20126	SANTA F	C	NONE	WEST BRAVO DOME UNIT #003	3	495	AMERADA	HES F-36-19N-29E	F	1980N	1980W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20059	SANTA F	C	NONE	WEST BRAVO DOME UNIT #002	2	495	AMERADA	HES F-30-19N-30E	F	1980N	1980W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20125	SANTA F	C	NONE	WEST BRAVO DOME UNIT #004	4	495	AMERADA	HES K-25-19N-29E	K	1980S	1980W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20127	SANTA F	C	NONE	WEST BRAVO DOME UNIT #005	5	495	AMERADA	HES K-31-19N-30E	K	1980S	1980W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20118	SANTA F	C	NONE	WEST BRAVO DOME UNIT #006	6	495	AMERADA	HES G-06-18N-30E	G	1980N	1980E	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20124	SANTA F	C	NONE	WEST BRAVO DOME UNIT #007	7	495	AMERADA	HES G-09-19N-29E	G	1980N	1980E	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20131	SANTA F	C	NONE	WEST BRAVO DOME UNIT #008	8	495	AMERADA	HES J-03-19N-29E	J	1980S	1980E	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20123	SANTA F	C	NONE	WEST BRAVO DOME UNIT #009	9	495	AMERADA	HES F-03-19N-29E	F	1980N	1980W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20129	SANTA F	C	NONE	WEST BRAVO DOME UNIT #010	10	495	AMERADA	HES G-33-20N-29E	G	1980N	1980E	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20128	SANTA F	C	NONE	WEST BRAVO DOME UNIT #011	11	495	AMERADA	HES K-32-20N-29E	K	1980S	1980W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20119	SANTA F	C	NONE	WEST BRAVO DOME UNIT #012	12	495	AMERADA	HES F-07-18N-30E	F	1980N	1980W	0	S		Roy Johnson-NMOC	1/1/02	50000	0	T	
30-021-20121	SANTA F	C	NONE	WEST BRAVO DOME UNIT #013	13	495	AMERADA	HES F-20-18N-30E	F	1980N	1980W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20143	SANTA F	C	NONE	WEST BRAVO DOME UNIT #014	14	495	AMERADA	HES F-29-19N-29E	F	1980N	1980W	0	F		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20142	SANTA F	C	NONE	WEST BRAVO DOME UNIT #015	15	495	AMERADA	HES F-21-18N-29E	F	1980N	1980W	0	F		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20191	SANTA F	C	NONE	WEST BRAVO DOME UNIT #016	16	495	AMERADA	HES G-33-19N-29E	G	1784N	2364E	0	F		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20229	SANTA F	C	NONE	WEST BRAVO DOME UNIT #017	17	495	AMERADA	HES F-18-19N-29E	F	1650N	1650W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20231	SANTA F	C	NONE	WEST BRAVO DOME UNIT #018	18	495	AMERADA	HES F-32-19N-30E	F	1650N	1650W	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-021-20233	SANTA F	C	NONE	WEST BRAVO DOME UNIT #020	20	495	AMERADA	HES A-13-18N-29E	A	990N	990E	0	S		Roy Johnson-NMOC	8/8/01	50000	0	T	
30-025-05808	HOBBS	G	08-1983	WILLIAMS #005	5	495	AMERADA	HES I-33-19S-37E	I	1980S	660E	3610	P		PBD @3028.MIT/passed	8/8/01	50000	0	A	
30-025-06129	HOBBS	G	03-1989	WOOD STATE A #001	1	495	AMERADA	HES C-16-20S-37E	C	660N	1650W		S		Pull A/L equip. set CIBP.MIT	11/1/01	50000	0	A	