

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP 080168
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL..... X	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 790 ft. from N line and 990 ft. from W line of sec. 21
10W/4 Sec. 21 (1/4 Sec. and Sec. No.) 27N (Twp.) 12W (Range) 10W (Meridian)
Basin Dakota (Field) San Juan (County or Subdivision) New Mexico (State or Territory)


The elevation of the ground level above sea level is 5700 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate casing job, cementing points, and all other important proposed work)

We propose to abandon subject well as follows:

1. Spot cement plug 6080'-5750' w/50 ex. across Dakota.
2. Spot cement plug 4900'-4800' w/20 ex. across Gallup.
3. Spot cement plug 1350'-1800' w/30 ex. across Pictured Cliffs.
4. Spot cement plug 40' to surface w/10 ex. Install permanent marker and clean location. Production casing was not run in well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tenneco Oil Co.
Address P. O. Box 1714
Durango, Colorado
By L.B. Flumb
Title District Production Supt.