

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR
Beta Development Co.
3. ADDRESS OF OPERATOR
125 Petroleum Plaza Farmington, N.M. 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:


SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE
SF-079116
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Edgar Federal
9. WELL NO.
4
10. FIELD OR WILDCAT NAME
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 15 27N-12W 14E
12. COUNTY OR PARISH 13. STATE
San Juan New Mexico
14. API NO.
15. ELEVATIONS (SHOW DE, KDB, AND W/D)
5901' G.R.

(NOTE: Report results of multiple completions and zone change on Form 9-331-C)



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

July 19 to 21.

Pull tubing check for leaks ran to 6100' squeeze 40 sacks into formation spot 35 sacks plug over perforation from 6038 to 56' and 6077 to 85' pull to 4300' and spot 60 sacks plug at base of Mesa Verde section lay down tubing work casing and shoot at 2154' pull and lay down 54 ft's 5 1/2" 15.5# casing run 2250' 2" tubing, spot 60 sacks plug 100' in and 100' out of casing stub at top of Mesa Verde section pull to 1800' spot 60 sacks at base of Pictured Cliffs pull to 465' spot 40 sacks plug pull and spot 10 sacks surface plug. All connection cut 4' below ground level, no dry hole marker required (Agricultural area).

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *D. E. Blanton* TITLE Superintendent DATE Sept. 7, 1978

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JAN 13 1981
James F. Sims
JAMES F. SIMS
DISTRICT OIL & GAS SUPERVISOR