

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Southwest Production Company	8. Farm or Lease Name Collier Federal
3. Address of Operator 1126 Mercantile Securities Building, Dallas, Texas	9. Well No. 1
4. Location of Well UNIT LETTER L , 1850 FEET FROM THE South LINE AND 790 FEET FROM THE West LINE, SECTION 18 TOWNSHIP 27N RANGE 12W N.M.P.M.	10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 5835 G. L.	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Squeezed perforations 5814-5914 (overall) with 150 sacks of cement. Tested to 3000#. Drilled out to 6030'. Perforated 6001-21 with 2 jets per foot. Tested salt water. Squeezed perforations 6001-21 with 50 sacks of cement. Tested to 3000#. Waiting on authority to plug and abandon well.

Shot 5½" casing at 1205' and pulled. Set cement plugs: 1160 - 1260; 260 - 360; 30' plug in surface casing. Erected dry hole marker. Completed 4-1-65.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Emery C. Arnold TITLE Agent DATE 4-1 9-65

Original Signed Emery C. Arnold APPROVED BY _____ TITLE Supervisor Dist. # 3 DATE APR 21 1965

CONDITIONS OF APPROVAL, IF ANY: