



(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Indian Agency Navajo
Allotted 1-149 Ind. 0146
Lease No. John Charles

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>Intermediate</u>	<u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of Setting of Liner</u>		<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 22, 1959

John Charles

Well No. 6 is located 895 ft. from [N] line and 1030 ft. from [E] line of sec. 13

NE 1/4 Section 13
(1/4 Sec. and Sec. No.)

27N
(Twp.)

9W
(Range)

N.M.P.M.
(Meridian)

Blanco Mesa Verde Nat. Park
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

1959

The elevation of the derrick floor above sea level is 5998 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran & set 7-5/8" OD casing at 2305' & cemented w/200 sks. reg. cement, 45 gal.

Ran temperature survey & found top of cement behind 7-5/8" OD casing at 1062'.

Ran & set 5 1/2" OD liner at 4498' w/top of liner at 2227', hung in Brown Oil Tool type "B" 14-new hanger. Cemented liner w/250 sks. cement, 50% pozzol w/1/4# floccs per sk. Drill pipe indicated cement circulated over top of liner.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY

Address Box 426
Farmington, New Mexico

By (Signed) P. E. Cosper

Title District Superintendent