

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Fed. 078094

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fullerton Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 15-27N-11W

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. NAME OF OPERATOR Gulf Oil Corporation	3. ADDRESS OF OPERATOR Box 670, Hobbs, N.M. 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL 1980' FEL Sec. 15-27N-11W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6321' GL		16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Well Status Report

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Last produced in 1973. Will repair casing leak and restore to production.

RECEIVED

OCT 17 1974

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

B. J. Barbary

TITLE

Area Engineer

DATE

10-15-74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS ROAD - AZTEC
87410

I. R. TRUJILLO
CHAIRMAN

LAND COMMISSIONER
ALEX J. ARMIJO
MEMBER

STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

November 27, 1974

Area Engineer
Gulf Oil Corporation
P. O. Box 670
Hobbs, New Mexico 88240


Re: Douthit Fed. #2, SW 27-27N-11W
Fullerton Fed. #5, NE 15-27N-11W
Fullerton Fed. #7, SW 11-27N-11W

Dear Sir:

We have received copies of Federal Sundry Report Form 9331 for the above wells stating that they have not produced for the past year. You further state that each well has a casing leak which you will repair prior to returning to production. You do not however state a time schedule for the accomplishment of these plans. Commission Regulations require that oil, gas and water zones be separated in producing or temporarily abandoned wells in order to prevent the possible contamination of fresh water, and to prevent the possible waste of oil and gas through reservoir damage or thru migration to other porous zones.

You are therefore directed to take immediate remedial action to repair the casing failures in these wells. We are instructing Mr. William Carr, Commission attorney to hold legal action in abeyance for 60 days from this date in order to give you time to take affirmative action.

Very truly yours,


Emery G. Arnold
Supervisor, District #3

cc: Mr. William Carr, OCC
U.S.G.S., Farmington, New Mexico

ECA/bk