

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 035634

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H. B. McGrady "A"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Undesignated Fruitland

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA
NW/4 Section 14,

T-27-N, R-12-W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☐ GAS ☐
WELL WELL OTHER **Dry Hole**

2. NAME OF OPERATOR

Moco Production Company

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, New Mexico 874014. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

790' FNL & 990' FwL, Unit "D"

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GL 5937', RKB 5947'

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

II. NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

I. SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒**Plug Back**(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*I. The subject well was plugged back from the Dakota formation and completed in the
Fruitland on January 25, 1971 as follows:

1. Spotted cement plugs 6244-5594' and 4350-4085'.
2. Set bridge plug at 1710' with cement plug 1710-1575'.
3. Ran Gamma Ray-Neutron Log and perfed 1228-38' with 2 SPF.
4. Fraced 1228-38' with 21,630 gallons treated water and 15,000 pounds 20-40 sand and 5,000 pounds 10-20 sand.
5. Ran tubing and swabbed in.

II. Due to the failure of the Fruitland zone to produce commercial quantities of gas,
we propose to permanently abandon the well as follows:

1. Spot cement plugs 1300-1200' and 100' to surface.
2. Attempt to squeeze annulus and bradenhead.
3. Erect PYA marker and clean up location for inspection.

4. spot plug 400-500 across alone.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Engineer

DATE

March 15, 1971

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.