

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER (Well is now plugged and abandoned)  
2. NAME OF OPERATOR  
Chevron U.S.A. Inc.  
3. ADDRESS OF OPERATOR  
P. O. Box 599, Denver, Colorado 80201  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1,690' FSL, 1,730' FWL

88 FEB 11 AM 10:14

FARMINGTON RESOURCE AREA  
FARMINGTON, NEW MEXICO

5. LEASE DESIGNATION AND SERIAL NO.

S.F. 078094

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Federal-Fullerton

8. FARM OR LEASE NAME

9. WELL NO.

Fullerton #7

10. FIELD AND POOL, OR WILDCAT

West Kutz-Basin Dakota

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

S. 11, T27N, R11W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6,129' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☒  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Due to severe casing damage, it is proposed to plug and abandon the Fullerton Federal #7 as follows:

1. Lay down workstring. N/D BOPE. N/U wellhead.
2. Fill 2-7/8" production casing from 976' to surface with 75 sx cement.
3. Install dry-hole marker. R/D and release rig.
4. Location to be rehabilitated.

Note: Prior to decision to abandon, production perfs at 6,441'-6,501' (Dakota) were squeezed through a CICR at 2,060' with 175 sx cement. Holes in 2-7/8" casing were squeezed with 680 sx cement (circulated cement to surface).

Verbal approval to plug and abandon was received from Ken Townsend with BLM in Farmington, New Mexico on January 7, 1988.

RECEIVED  
FEB 11 1988  
OIL CON. DIV.  
DIST. 3

6 - BLM  
1 - EEM  
1 - JTC  
3 - Drlg.  
1 - File

18. I hereby certify that the foregoing is true and correct

SIGNED

*J. Watson*

TITLE Technical Assistant

DATE February 5, 1988

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*alt*

\*See Instructions on Reverse Side

NMOCO