Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

	A market and a second a second and a second			
SUNDRY NO	5. Lease Designation and Serial No.			
	SF-077329			
Do not use this form for prop	6. If Indian, Allottee or Tribe Name			
Use "APPLIC	ATION FOR PERMIT - " for such proposals"			
and the state of t		7. If Unit or CA, Agreement Designation		
1. Type of Well Oil Well Well Other				
		8. Well Name and No.		
2. Name of Operator	Attention:	E. E. Martin "B" #1		
Amoco Production Company	Gail M. Jefferson, Rm 1942	9. API Well No.		
3. Address and Telephone No. P.O. Box 800. Denver. Coloredo. 80201 (303) 830-6157		300450664900		
P.O. Box 800, Denver, Colorad	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or	Survey Description)	Fulcher Kutz Pictured Cliffs		
1700FSL 1735FWL Sec. 10 T 27N R 10W Unit K		11. County or Parish, State		
		San Juan New Mexico		
12. CHECK APPROPR	ATE BOX(s) TO INDICATE NATURE OF NOTICE, R	REPORT, OR OTHER DATA		
TYPE OF SUBMISSION				
Notice of intent	Abandonment	Change of Plans		
Notice of Intent	Recompletion	New Construction		
	Plugging Back	Non-Routine Fracturing		
Subsequent Report	Casing Repair	Water Shut-Off		
Final Abandonment Notice	Altering Casing	Conversion to Injection		
This Abardownian House	Other	Diapose Water		
	Recompletic	ort results of multiple completion on Well Completion or on Report and Log form.)		
	requests permission to plug and abandon the above referenced stions please contact Mike Kutas at (303) 830-5159 or myse			
		MAI I 7 WOU		
		OH COM. DHV. Det. 3		
14. I hereby certify that the foregoing is true and	Serrect Here Sr. Admin. State	ff Asst. Date 05-14-1995		
This space for Federal or State office use)	10			
		rest of the terms		
Approved byConditions of approval, if any:	Title	ASMINDED		
Title 18 U.S.C. Section 1001, makes it a crime fo	r any person knowingly and willfully to make to any department or agency of the United State	as any tates, ficticious for fraudulent pretamont for		

E. E. Martin B #1
Orig. Comp. 8/51
TD = 2235', PBTD = 2155'
Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 1 1/4" tbg. RIH with tbg and cement retainer. Set retainer at 2075'. Test casing integrity to 500#.. Squeeze perfs at 2131' to 2149' with 13 cuft of cement. Pull out of retainer and spot cement plug to 1800' with 16 cuft cement.
- 4. Pull up hole and spot cement plug from 1157' to surface with 60 cuft cement.
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

		Amoco Production Comp	any	Sheet No. File	Oi
SUBJECT_	EUAE. MARTIN 8 1		and the second s	Date 12-29-	
				By GM KUTA	<u> </u>
					•:
		7/1			
	A	1034" csa 106"			
		cmi w/75 sx5 -	circulateo		
		W κ	BWREV COMMENTS DREW DOWN TO AC WH PRESSURE; U GMK TO EVALUATE	TESTED THING, SI FIRE LESSON 2 Auto, FUR ROA	ou Comp- iusufficient no Equip
Pear	——————————————————————————————————————	2.3# L. 31/2 "CSA 217" cont circid 9.3 # J55 51/2 "CSA 2133" 14 # J55	r w x-pin on btm		
PC 2131-	49	CMT W/75 5x3 CM	11		
	XX	QH. TO 2235, PBD = 7	2207		,
	P8D - 2	153	<u>:</u>		
					· · · · · · · · · · · · · · · · · · ·
				•	
					: 1

.

:

1