


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION

DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079116
Unit KOH



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Completion Report.....	XX

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 21, 1951, 19

Well No. Hancock is located 1650 ft. from N line and 1650 ft. from E line of sec. 12

SW 1/4 Sec. 12 27N 12W N.M.P.M.
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
West Kutz Canyon San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6045 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well completed on 5-26-51. 1" Tubing and Xmas tree hook-up installed.
Total depth 1772 feet. Well tested 2,630 MCF/day on test made by
Southern Union Gas Company.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company JAMES D. HANCOCK & COMPANY, LTD.

Address 916 Kirby Building

Dallas, Texas

By J. D. Hancock Jr.

Title General Superintendent

[illegible][illegible]

If _____ at least one word is left blank and the letter "X" is placed in the

DEFINITION OF WORK

1. The first of these is the fact that the Commission has not yet received any information from the Member States as to the progress of the implementation of the Directive. This is a serious matter, and it is the Commission's duty to ensure that the Directive is implemented in a timely and effective manner.

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

I understand that this plant of work must receive a copy of _____

Company _____
Address _____

By _____

JAN _____