GPO 862040

4-4	
1-ND	
1-D	
1-F	

Form 9-331 a (Feb. 1951)

	 X	

(SUBMIT IN TRIPLICATE)

UNITED STATES **DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY**

Budget Bureau No. 42-R358.4. Approval expires 12-31-60.
Land Office
Lease No. SF-078935
Unit Thompson Federal

SUNDRY	NOTICES	AND	REPORTS	ON	WELL	S	Ą	F	[] <u>[</u>	/ F	
						Est	1.1	1 **;	· 11	.' <u>L</u>	

		EPORTS ON WELLS	is/ Lisa B - u
NOTICE OF INTENTION TO DRILL		QUENT REPORT OF WATER SHUT-OFF	40
NOTICE OF INTENTION TO CHANGE PLAN	l il	QUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER :	SHUT-OFF SUBSE	QUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR	REPAIR WELL SUBSE	QUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR AC	CIDIZE SUBSE	QUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR AL (ER CASINGSUPPL	EMENTARY WELL HISTORY	-X
NOTICE OF INTENTION TO ABANDON WEI	LL		
(INDICATE A	ABOVE BY CHECK MARK NATURE OF	REPORT, NOTICE, OR OTHER DATA)	
	<u></u>	February 27,	, 19.62
	 	e and _1850 ft. from $\left\{ egin{align*}{c} E \\ W \end{array} ight\}$ line of	sec10
SHAME Sec. 10 (1/4 Sec. and Sec. No.)	27 N 12 M (Twp.) (Range)	(Meridian)	
Besin Dakota (Field)	Gounty or Subdivision	Mari So	
(FIGNI)	(County of Editorialists	(State of Territory)	
T.D. 6210. Ran & s	ing points, and all other imports	int proposed work)	a+ &
7.D. 6210. Ran & s 6199, DV tool 8 182 sx 50/50 mmix 4% o	ing points, and all other imports pet 196 jts. 6202' 4 27, float collar # 6 tel. 100 sx mest 1% i	10.50# Lone Star csg. sci 179. Comented 1st stage w halad #9, plug down 12:00 1 4% gel, plug down 9 12:30	et @ /200
ex 50/50 mmix 4% g 25th. 2nd stage w/ 25th. MCC. I understand that this plan of work mu	ing points, and all other imports pet 198 jts. 6202' 4 27, fleet collar 9 6 pel, 100 ax meet 1% i 150 ax 50/30 pozmix ust receive approval in writing by the	10.50# Lone Star cag. selection of the cape with the cape	200 noon P.M.
T.D. 6210. Ran & s 6199, DV tool \$ 182 sx 50/50 mmix 4% g 25th. 2nd stage w/ 25th. WGC.	ing points, and all other imports pet 198 jts. 6202' 4 27, fleet collar 9 6 pel, 100 ax meet 1% i 150 ax 50/30 pozmix ust receive approval in writing by the	10.50# Lone Star cag. selection of the cape with the cape	200 noon P.M.
T.D. 6210. Ran & s 6199, DV toel \$ 182 sx 50/50 mmix 4% g 25th. 2nd stage w/ 25th. WGC.	ing points, and all other imports pet 198 jts. 6202' 4 27, float collar 9 6 pel, 100 sx neet 1% i 150 sx 50/30 pozmix ustreceive approval in writing by the state of the	10.50# Lone Star csg. colors 179. Comented 1st stage whalad #9, plug down 12:00:4% gel, plug down # 12:30 MAR 2	200 noon P.M.