

Charlie Hosh #1

2/12/91 - 2/20/92

MIRUSU, RU pump and killed well W/40 BBls 2% KCL wtr. TIH with 5jts 2.375" TBG & tagged bottom @ 6056' W/ K.B. TIH with 4.5" CSG scraper to PBTD. TIH with RBP, PKR & TBG to 5885'. TOH W/1std tbg and set PKR @ 5850'. RU pump and press tested plug to 1000psi. plug held press. Released PKR and loaded CSG. Press. tested CSG to 1000psi. csg held. TOH with TBG & PKR. RU WLE. & TIH W/CBL CCL GR logged interval 4210' to 200'. RU squeeze gun and perf @ 430' W/2 JSPF 1'. TOH W/gun. RU pump & pumped down csg 20 BW, to get circ. through B. Head. Circ B. Head clean. RU CMT. Pumped 10BW to establish rate and press. Mixed and pumped 210sxs CL B cmt W/2% CACL @ 3 BPM and 500psi. Pumped 6 BW displacement. SI Bradenhead and press. well to 800psi, watched well for 15 min. W/ no bleed off. TIH and tagged cmt @ 383'. Drilled cmt from 383' to 440'. RU pump and press. test csg to 600psi. Held. TIH with RET. Head & TBG and circ sand off of plug. TOH with TBG, RET. head & RBP. TIH W/Prod string & landed TBG @ 5979' W/ K.B. NDBOP. NUWH. return to Prod.



