Form 3160-5 (November 1983) (Formerly 9-331)		UNITED STATES SUBMIT IN TRIPLICATED DEPARTMENT OF THE INTERIOR (Other Instructions on re-		Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEARS DESIGNATION AND SERIAL NO. SF-080382	
	SUNI (Do not use this i	6. IP INDIAN, ALLOTTER OR TRIBE NAME			
ī.	OIL GAB (X office		7. UNIT AGREEMENT NAME	
2.	NAME OF OPERATOR			8. FARM OR LEASE NAME	
		Southland Royalty Compa	Santa Fe G		
3.	ADDRESS OF OPERATOR		9. WELL HO.		
		Post Office Box 4289, Fa			
4.	LOCATION OF WELL (Re	port location clearly and in accordance with any	10. FIELD AND POOL, OR WILDCAT		
	At surface	port location clearly and in accordance with any 790 S, 790 W	Kutz Gallup		
	·			11. SEC. T. E., M., OR BLE. AND SURVEY OR ARMA Sec. 5 , T-27-N, R-11-W N.M.P.M.	
14.	PERMIT NO.	BRMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE	
	6105'GL			San Juan NM	
16.		Check Appropriate Box To Indicate N	Other Data		
	no	OTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
	TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER OFFICE]	

SHOOT OR ACIDIZE SECOTING OR ACIDIZING CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)

MULTIPLE COMPLETE

FRACTURE TREAT

This well was approved for plug & abandonment on February 11, 1986. has been delayed until August 1, 1988. Please cancel this plug & abandonment approval.

PRACTURE TREATMENT

REPAIRING WELL

ALTERING CASING

It is requested that the well be plugged back and recompleted to the Fruitland coal as follows:

Pull rods & pump and lay down. Release packer, pull tbg. and lay down. Spot 54 sx (64 cu.ft.) cement plug 5891-5422' over Gallup. squeeze holes @ 3500', set retainer and squeeze 28 sx (33 cu.ft.) cement 3500-3400' across Cliff House. Perf squeeze holes @ 2820', set retainer and squeeze 28 sx. cmt. across Chacra. Set retainer at 1850', sting into retainer and fill w/13.5 bbls. of 9#, 50 vis gel mud. casing to 2500 psi and squeeze any holes in casing as needed. Recomplete to coal interval approximately 1825-1845'.

18. I hereby certify that the foregoing is true and co	orrect	25		
SIGNED SIGNY STALL	TITLE _	Drilling Clerk(CB)	DATE	06-29-88
(This space for Federal or State office use)			P-	
APPROVED BY	TITLE _	0/1 00/1 1988	A PP	ROVED
	*See Instructi	ons on Reverse Side 3	J U	7 1988 2 KILL