

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078935

Unit SE/4 Sec. 2, T27N, R12W

RECEIVED

JUL 20 1951

OIL CON. COM.

DIST. 3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 26, 1951

Well No. 2 Thompson is located 990 ft. from INT line and 990 ft. from E line of sec. 2

SE/4 Sec. 2
(1/4 Sec. and Sec. No.)
West Kuts Canyon
(Field)

T-27N, R-12W
(Twp.) (Range)
San Juan County
(County or Subdivision)

100M
(Meridian)
New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5953 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On July 18th the well was drilled to 1670' at which depth the well was shut (and it was found that communication was had between 5-1/2" and 8-5/8" surface casing. Drilled to a total depth of 1752', the well was killed, calseal plug set at 1587' and a Halliburton IERP tool was run to 30' off bottom and tested 30' for 90' and 60' to 199 with 600# after defect in casing was found. Pulled tool to 168 and pumped 1 60 sacks cement circulated 2 barrels to surface and squeezed with 500#. Found 50' cement 168 to 518, cleaned to calseal plug. Pressured up and found squeeze job satisfactory.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Danube Oil Company
Address 213 First National Bank Bldg.
Amarillo, Texas

By Joe Lilly
Agent