## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

			<del></del>		<del> </del>	
		Sundry Not	ices and Reports of	on Wells		
		10) E	CEIVEN .	- 1 - 5 - FH 0 - 63 - 5.	Lease Number	
		int	1111		AT ATACTOS	
1. <b>Ty</b>	pe of Wel	ւլ ըս	IAN 20 1998 🗩 🖟		If Indian, All. or	
	GAS		·	,, J : . ·	Tribe Name	
			CCH. DIV.			
			District (2)	7.	Unit Agreement Name	
2. <b>Na</b>	me of Ope	erator				
Ę	WRL.	INGTON OF				
r	ŒSO	ORCES OIL	& GAS COMPANY			
				8.		
		Phone No. of Opera	_	Frontier B #4		
P	O Box 428	39, Farmington, NM	-9700 9.	API Well No.		
4 70		f Wall Backson C			30-045-06812 . Field and Pool	
		f <b>Well, Footage, S</b> 90'FWL, Sec4, T-2		10	Kutz Gallup	
,,,	O F3L, 3.	30 FMH, Sec.4, 1-2	/-N, K-II-W, NMPM	11	. County and State	
					San Juan Co, NM	
	Fir	nal Abandonment	Casing Repair Altering Case Other -	ir Water Shut sing Conversion		
13.	Describe	e Proposed or Comp	oleted Operations			
	5-30-97	(Verbal approval BLM).	. to plug well aft	er corn crop harvest	ed from Wayne Townsend,	
		MIRU. TOOH w/rod				
	12-2-97				/120 jts 2 3/8" tbg.	
	Tbg parted. (Verbal approval to change plans from Steve Mason, BLM). (Ton outside csg @ 4080'. TIH w/fishing tools. TOOH. (Verbal approval to change plans from Steve Mason, BLM). TIH w/chemical cutter. Cut tbg @ ! SDON. (M. Deaton, BLM on location).					
12-3-97 TOOH w/tbg & fishing tools. (Left 4 jts tbg in well). TIH, e Plug #1: pump 75 sx Class "B" neat cmt inside csg @ 5153-5					TIH, establish circ.	
	tag TOC @ 5215'. TOOH to 2919'. Perf 3 sqz holes @ 29				2919'. TOOH. TIH w/cmt	
					: pump 30 sx Class "B"	
				9'. Pump 17 sx Class	"B" neat cmt inside cs	
		TOOH to 1999'.				
·		Continued on back  I hereby certify that the foregoing is true and correct.				
14./	I hereb	y certify that the	foregoing is tru	e and correct.		
Signe	a Deggy	Daahue	Title Regulat	ory Administrator Da	te 1/5/98	
(This	space f	or Federal or Stat	ce Office use)		<u> </u>	
APPRO	VED BY	/S/ Duane W. Spence	Title	Date	JAN 15 L	
	_	APPROVAL if any:				

- 12-4-97 Establish circ. Plug #3: pump 41 sx Class "B" neat cmt inside csg @ 1681-1999'. TOOH to 896'. PT csg to 500 psi/15 min, OK. TOOH. TIH, perf 3 sqz holes @ 960'. TOOH. TIH w/cmt retainer, set @ 896'. Establish injection Plug #4: pump 57 sx Class "B" neat cmt outside csg @ 767-960'. Pump 28 sx Class "B" neat cmt inside csg @ 765-960'. TOOH. TIH, perf 3 sqz holes @ 223 Establish circ down csg & out bradenhead. Plug #5: pump 130 sx Class "B" neat cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. SDON. (M. Deaton, BLM on location).
- 12-5-97 ND BOP. Cut off WH. Install dry hole marker w/10 sx Class "B" neat cmt. RD. Rig released. (M. Deaton, BLM on location). Well plugged and abandoned 12-5-97.

Office State