

COPY FOR  
STATE OF NEW MEXICO  
OIL CONSERVATION  
COMMISSION  
SUBMIT IN TRIPLICATE TO  
DISTRICT OFFICE

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078935

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

AUG 18 1951  
OIL CONSERVATION  
DISTRICT

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 11, 1951

Well No. 3 Thompson is located 1650 ft. from N line and 990 ft. from E line of sec. 3

SE/4 Sec. 3 27N 12W RMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
West Kutz Canyon San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5908 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

The well was shot 8-5-51 with 205 qts. of solidified nitro glycerin from 1561-1645.

The shot went off on time and the calseal plug was drilled and the well cleaned out to bottom, and the well was estimated to be making 4-1/2 mcfg.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Danabe Oil Company

Address 213 First National Bank Building

Amarillo

Texas

By [Signature]

Title Agent