

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Meridian Oil Inc.	8. FARM OR LEASE NAME Thompson C
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650'S, 990'E	10. FIELD AND POOL, OR WILDCAT W. Kutz Pic. Cliffs
14. PERMIT NO.	11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA Sec. 3, T-27-N, R-12-W N.M.P.M.
15. ELEVATIONS (Show whether OF, RT, GR, etc.) 5908' GL	12. COUNTY OR PARISH 13. STATE San Juan NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐

(Other) _____
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. (See REVERSE SIDE OF COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.))

The following is the revised intended procedure to plug & abandon this location during the second quarter 1988:

MOL&RU. Circulate hole w/9.2# mud. Spot 73 sx (91 cu.ft.) Class "B" neat cement to cover open hole and bottom casing to 1197'. WOC. Tag plug. Displace hole w/9.2# mud. Perforate holes @ 471' and 140'. Set retainer at 270' and squeeze 55 sx (64 cu.ft.) Class "B" neat cement under retainer. Displace hole w/9.2# mud. Circulate 52 sx (61 cu.ft.) Class "B" neat cement to surface. Cut off wellhead and set plug & abandonment marker.

RECEIVED
BLM MAIL ROOM
FEB -3 PM 2:05
BUREAU OF LAND MANAGEMENT
FARMINGTON, NEW MEXICO

RECEIVED
OIL CON. DIV.
FEB 11 1988
FARMINGTON, NM
60000-02-38

I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Drilling Clerk DATE 1988-02-38

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOCC