5-1142

DEPARTMENT OF THE INTERIOR

United States Indian Field Service

Washington.

Producers & Refiners wish to abandon Table
Mesa well and have offered it to Indian Office as
mater well for \$20000.00, price being quoted as
half value of material to be left in well. It
occurs to me that one string of pipe if properly
seated preferably cemented would be adequate for
water well thus allowing Producers to pull remaining
pipe. Tou may find it necessary to fill bakk of
pipe with mud as outside strings are pulled. If
other strings are frozen I consider it hard luck
for operators but no reason for us to buy pipe
because it cannot be removed. Please make careful
investigation and cooperate with Kneale reporting
soon as practicable your recommendation.

Tough.