

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
SF-080382-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Frontier "C"

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Kutz-Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY AREA
Sec. 9, T27N, R11W, NMPM

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER
2. NAME OF OPERATOR
El Paso Natural Gas Products Company
3. ADDRESS OF OPERATOR
Post Office Box 1560, Farmington, New Mexico 87401
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980'/N, 990'/W, Section 5, Township 27 North, Range 11 West

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6092' D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☒

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐



ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well is to be abandoned in the following manner:

- 1. Set 25 Sk. Cement Plug from 5750' to 5950' (Perforations 5800'-5892')**
- 2. Set 30 Sk. Cement Plug across 5-1/2" Casing Stub. (Top of cement at 1600', Top of Fruitland 1577'.)**
- 3. Set 40 Sk. Cement Plug from 700'-800' (Ojo Alamo 712'-805')**
- 4. Set 10 Sk. Cement Plug at Surface w/Dry Hole Marker.**



18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed EWELL N. WALSH

TITLE

Division Petroleum Engineer

DATE

October 13, 1965

(This space for Federal or State office use)

APPROVED BY EW

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.