

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Beta Development Company

3. ADDRESS OF OPERATOR
238 Petroleum Plaza, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1650' FNL & 1650' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6050' G.L. FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.
SF-079116

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Edgar Federal

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 1 T-27N, R-12W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

RECEIVED
JAN 28 1987

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>

(Other) Amended Sundry Notice 3-25-86 ☒ X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to dual complete Gallup & Dakota
To repair casing as approved sundry notice 4-11-86 just as planned after testing the Dakota sandstone, perforate the Graneros section @ (6332-40, 6358-62) 2 shots per ft. acidize and test, set bridge plug 6200' + or -, perforate Gallup section (5604-08, 5656-58, 5674-78, 5696-70, 5731-33, 5738-42, 5754-60) 2 shots per ft, acidize and test.
Recover all bridge plugs, clean out to original T.D. (6470').

18. I hereby certify that the foregoing is true and correct

SIGNER D. E. Bayter
(This space for Federal or State office use)

TITLE Superintendent

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

APPROVED

DATE January 27, 1987

FEB 03 1987

DATE Jan 27 1987

for AREA MANAGER
FARMINGTON RESOURCE AREA