

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

ST 078019

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

S. M. Pipkin

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Fletcher East-Pick. Cliffs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

NE/4 Section 1,

T-27-N, R-11-W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

1. OIL ☐ GAS ☐ OTHER ☒
WELL WELL

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

P. O. Box 483, Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FWL & 990' FWL

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5733' GL

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Due to uneconomical production the well was treated as follows:

1. 3-15-67 - $P_c = 185$ psi.

A. Put 35 gallons Nutro Prep down 7" casing and 20 gallons Nutro Prep down 1" tubing.

B. Well shut in 7 hours, $P_c = 210$ psi. Blow down well and unload water and mud.2. 3-16-67 - Shut in 14 hours. $P_c = 280$ psi.

A. Put 20 gallons Nutro Prep down 7" casing and 10 gallons Nutro Prep down 1" tubing.

B. Shut in one hour and blow down 10 minutes to unload mud and water.

3. 3-17-67 - Shut in 24 hours. $P_c = 410$ psi.A. Blow 10 minutes to unload mud and water and $P_c = 250$ psi.B. Blow total of one hour and $P_c = 180$ psi.4. 3-20-67 - Shut in 72 hours. $P_c = 420$ psi.

A. Run test as reported on Form G-104 with 55 MCFD production at 260 psi.

18. I hereby certify that the foregoing is true and correct

SIGNED

G. J. Eaton, Jr.

TITLE

Area Engineer

DATE

June 12, 1967

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated on Federal and Indian lands, private and unappropriated Federal and unappropriated Indian lands, and on all lands in such States as require a permit to drill a well. State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

