Form 3100-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND MANAG		Expires: March 31, 1993		
SUNDRY NOTICES AND REPORTS ON WELLS			Lease Designation and Serial No.	
			SF-07830 6 -A	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals		6. If Indian,	Allottee or Tribe Name	
OSO ATTEMATION TONTENINT - 101 Su	cii proposais			
		7. If Unit or	CA, Agreement Desig	nation
1. Type of Well				
Oil Gas Other		8. Well Nam	e and No.	
2. Name of Operator Amoco Production Company	Attention:		Bolack A	#1
Amoco Production Company Gail M. Jefferson, Rm 1295C Address and Telephone No.		950		114
P.O. Box 800, Denver, Colorado 80201	(303) 830-6157		3004506914 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Basin Dak	
700FNI 47F0FFI 0 0 7 T 0	7N D 44W	11. County	or Parish, State	
790FNL 1750FEL Sec. 2 T 2	7N R 11W Unit B		San Juan	New Mexico
CUECK APPROPRIATE POW 1 TO INDIO	ATE MATURE OF MOT			
12. CHECK APPROPRIATE BOX(s) TO INDICA			OR OTHER DA	ATA
TYPE OF SUBMISSION	TYPE OF A	ACTION		
	pandonment	Charact Riv		
X value of the control of the contro	completion	Change of Pl		
[]	ugging Back	Non-Routine	Fracturing	
	ising Repair tering Casing	Water Shut-0		
Final Abandan and Nation	her	Conversion to		
		(Note: Report results of me Recompletion Report and I	ultiple completion on W Log form.)	ell Completion or
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give subsurface locations and measured and true vertical depths for all markers and zones; Amoco Production Company requests permission to plug If you have any questions please contact Gail M. Jefferso	ertinent to this work.)* and abandon the above re			-
	DECEL N sep - 8 OIL CON Divid	IVED 1995 D	53 AMG 32 AM IO: 55 070 Familia ION, NM	SECEIVED RECEIVED
14. I hereby certify that the foregoing is true and correct	C- Ad	min Staff Anat		08-31-1995
Signed	Title Sr. Adl	min. Staff Asst.	Date	00-31-13:55
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	APP	POVE	D
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to ma representations as to any matter within its jurisdiction.	ske to any department or agency of the	United States any false, fin	ticious, or fraudulent s	tatements or

* See Instructions on Reverse Side

C DICTETO MAD AGE

Bolack A #1 Orig. Comp.7/60 TD = 6490', PBTD = 6460' Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill with fresh water. NDWH. NUBOP.
- 3. Run free point on 2 3/8" tbg. Load back side and establish injection rate into 2 3/8" tbg. (besure the tbg is not leaking) Note: If unable to establish rate please contact the Denver office. Cut 2 3/8" tbg at free point. TOOH. RIH with 7" cement retainer and set above free point. Run short string CBL on 7" casing. Test casing integrity to 500#. Squeeze below cement retainer with est. 199 cuft of Class B neat cement.
- 4. Run in hole with perf gun and shoot squeeze holes at TOC and attempt to circulate with water to surface. Circulate with cement. If unable to circulate besure the following is covered 100' inside and outside casing:

Fruitland at 1553' Ojo Alamo at 722' and 274' to surface


- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Contact FMC and ship surface equipment to yard or other location per instructions.
- 7. Turn over to John Schwartz for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

Amoco Production Company

ENGINEERING CHART

SUBJECT	Bolack A =11	
	Sec. 2 TOTA-RILLI)	

heet No	Of
1 110	
Date	5/24/95
Bu	JLU)



To: Carolanne Wyett	Date FAXSent: 8/16/95
From . Chip Harraden Geologist	FAX #: 303 -830-4777
Farmington Dist. Off-BLM Phone: 505-599-6361	
Here are the Formation tops for the	Rolark A#1 well. 790 FNL, 1750 FEL Sec. 2 27N-11W G15983' KB 5995'
	GL 5983' KB 5995'
	TD 6508' SF-078304A
Santose	
Nacimiento Surface	
Ojo Alamo 722'	
Kirtland 822'	
Enitland 1553'	
Pictured Cliffs 1833'	
Lewis 1933'	
Chacra 2753'	
CliffHouse 3385'	
Monetee 3492	
· Paint Lookout 4232'	
Mancos ' 4562'	
Gallup 5409'	
Pakota 6382' to TD	
Morrison	The second secon
	Thanks,
	Chip Hanaden
OPTIONAL FORM 89 (7-90)	
FAX TRANSMITTAL of pages > 1061	
Arolanne Wyett ChipHarladen Phone # 505-599-6361	
303-830-4777 Fax " 505- 599-8998	
NSN 7540 01-317-7398 5099 101 GENERAL SERVICES ADMINISTRATION	and the second s