UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

MULTIPLE COMPLETE CHANGE ZONES

Form 9-331	Budget Bureau No. 42-R1424
Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF078895 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other	o WELL NO
2. NAME OF OPERATOR	8 10. FIELD OR WILDCAT NAME West Kutz P.C. DIST. 3
3. ADDRESS OF OPERATOR 1000 Petroleum Building - Denver, CO 80202 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 990' FNL, 990' FWL (NW4 NW4) AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 6-T27N-R11W 12. COUNTY OR PARISH 13. STATE San Juan NM 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6053' GR
PULL OR ALTER CASING 以 岩	E CE change of Form 9-330.)
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL REPAIR WELL REPAIR WELL	E Charge of Form 9-330.) AUG 2 6 1983

BUREAU OF LAND MANAGEMENT. ABANDON* (other) Request for Temporary SI Status FARMINGTON RESOURCE AREA 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is requested that a continuance of the current shut-in status of the subject well be granted for an indeterminate period of time for the following reason:

The results of the recompletion of the Mudge "A" No. 7 (NW_4^1 SW $_4^1$) Sec. 6-T27N-R11W) were to have determined the feasibility of pursing a similar course in the case of the subject well. (See Sundry Notice From 9-331 for subject well approved May 10, 1983). The degree of success achieved by recompleting the Mudge "A" No. 7 is unknown since the gas purchaser, to date, has failed to provide a production sales outlet. Until the Mudge "A" No. 7 has been on producing status for a sustained period of time, the economic practicality of recompleting the subject well will remain a moot question.

WIII Temain a most questi	This Approval Or Temporary
Subsurface Safety Valve: Manu. and Type	Abandonment Expires
SIGNED WWW. Shullwith P	rod. Supt So. DateAddust 23; Rockies
(This space for	r Federal or State office use)
APPROVED BY TITLE	DATE
CONDITIONS OF PARTIES	The things

*See Instructions on Reverse Side