Form 9-331 a (Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

| Land Office | Santa 70 |
|-------------|------------|
| Lease No | 078895 |
| | 360 |
| AP. | R 2 1952 |

U. S. GEOLDOLOM SHRVEY

| (Field) | or above sea level is 602k.1 | |
|--|------------------------------|---|
| mane reas combon (exi) | (County or Subdivision) | (State or Territory) |
| (1/4 Sec. and Sec. No.) | Sen Jean | (Meridian) Row Neggloo |
| III of Sec. 6 (14 Sec. and Sec. No.) | 27 H 11 W | |
| Hadge "A" | ed 990 ft. from Nine an | Harch 26 , 19 |
| OTICE OF INTENTION TO ABANDON WELL | L | Techno JIO |
| OTICE OF INTENTION TO SHOOT OR ACII | R CASING SUPPLEMENTA | 1/ APR 1 / 1059 |
| OTICE OF INTENTION TO RE-DRILL OR R | | REPORT OF REDRILLING OR PAPARALLE REPORT OF ABANDONMENT |
| OTICE OF INTENTION TO TEST WATER S | | REPORT OF ALTERING CASING |
| 01104 01 1111-1111011 10 01-1110-1-1-1 | S SUBSEQUENT | REPORT OF SHOOTING OR ACIDIZING |

Propose to drill with rotary tools well of sufficient depth to test Pictured Cliffs formation at approximately 1800 feet. Expect to set approximately 100 feet of 8-5/8", 9-5/8", 10-3/4" or 13" surface coming and approximately 1800 feet of 5% or ?" production easing. Surface easing will be comented to surface and production casing will be commuted with not less than 50 sacks. If considered desirable to increase production potential, will plan to shoot well with mitro-glycerine. Propose to drill in and complete the well with cable tools. Copies of any logs obtained will be furnished to WOS.

ME; of Section 6 is Designated Drilling Unit.

| JAMES D. HANCOCK & COSTANY, 15 | the Geological Survey before operations may be commenced. |
|--------------------------------|---|
| 916 Kirby Building | |
| Dallas, Texas | By O. F. Stances |
| | Title Asst. Superintendent |