

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-077941-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

C. A. McAdams "D"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 20, T 27 N, R10W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6201 RDB, 6189 GR

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) **Supplementary History**

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled to 370. Cemented 8 5/8" 24# j-55 ST&C casing at 370 with 220 sacks type "C" with 2% cacl. Drilled to TD 6562. Set 4 1/2" 10.5# j-55 ST&C casing at 6562 with Stage tool at 4740. Cemented first stage with 400 sacks type "C" with 6% gel with 2lbs tuf plug/sack followed by 100 sacks type "C" Neat. Cemented second stage with 1000 sacks type "C" with 6% gel with 2 lbs tuf plug per sack. Displaced hole with water containing .6% Kel with 2 1/2 lbs FR-8 per 1000 gal. Shotted 500 Gal acid. Perforated 6476-6486 with 6 shots/ft. Fraced with 39,360 gal water treated as above with 30,000 lbs 20-40 sand and 10,000 lbs 10-20 sand. Breakdown pressure 2900. Treating pressure 3300 at 62 1/2 bbls/Min. Set bridge plug at 6450. Perforated 6421-29 and 6388-98 with 3 shots/ft. Fraced with 40,330 gal water treated as above with 30,000 lbs 20-40 sand and 10,000 lbs 10-20 sand. Breakdown pressure 2700. Treating pressure 3300 at 61 1/2 bbl/Min. Drilled out bridge plug and cleaned out to PBD 6530. On 12/1/65 well flowed at the rate of 5071 MCF/Day on a 3/4" choke. TPF 409. CPT 844.

RECEIVED

DEC 22 1965

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

RECEIVED

DEC 23 1965

OIL CON. COM.

DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

D. I. Tellefsen

TITLE

Administrative Assistant

DATE

12/16/65

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.