

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

070 FARMINGTON, NM

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Amoco Production Company

Attention:

Pat Archuleta, Room 1205C

3. Address and Telephone No.

P.O. Box 800, Denver, Colorado 80201

(303) 830-5217

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1190'FSL 660' FEL

Sec. 31 T 28N R 8W

Unit P

5. Lease Designation and Serial No.

SF-079319

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Schwerdtfeger A 4

9. API Well No.

3004511893

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

San Juan

New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☒ Altering Casing
☐ Other
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRUSU 5/21/96.

Tag to verify depth of perf, tagged at 7410'. Set RBP to test for casing leak at 4995'. Squeezed casing leaks at 3131'-3220', first cement all went into leak, waited 24 hrs., squeezed again w/200 sks class B cement, squeezed to 300#. Drilled out squeezed cement to repair casing leak, tested to 500#, held okay. Cleaned out to 7494', pick up with 11/4" and 11/2" tubing. Did not reperf.

RDMOSU 6/4/96

If you have any technical questions contact Mark Rothenberg at (303) 830-5612.

14. I hereby certify that the foregoing is true and correct

Signed

Pat Archuleta

Title

Clerk

(This space for Federal or State office use)

Approved by

Title

Conditions of approval, if any:

AUG 01 1996

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD

FARMINGTON DISTRICT OFFICE
BY [Signature]