
Form 3160-5 (November 1983) (Formerly 9-331)	DEPARTMENT O	STATES OF THE INTERIC ND MANAGEMENT	SUBMIT IN TRIPLICATE* (Other Instructions on re- verse side)	Budget Bureau N Expires August (5. LEASE DESIGNATION A SF-078094 6. IF INDIAN, ALLOTTEE	31, 1985 AND BERIAL NO.
SUNDI	RY NOTICES AS TO THE PROPERTY OF THE PROPERTY	ND REPORTS O or to deepen or plug ba PERMIT—" for such pro	N WELLS ck to a different reservoir. posals.)		
1.				7. UNIT AGREEMENT NAM	4 E
WELL WELL	OTHER		; fts	8. FARM OR LEASE NAM!	<u> </u>
2. NAME OF OPERATOR	Fullerton Federal				
	nneville Fuels	Corporación		9. WELL NO.	
160	3. ADDRESS OF OPERATOR 1600 Broadway, Suite 1110, Denver, CO 80202				
4. LOCATION OF WELL (Rep-	10. FIELD AND POOL, OR WILDCAT				
See also space 17 below. At surface)			Basin Dakota	
	1650′	FNL, 990' FWL		11. SEC., T., E., M., OR BI SURVEY OR AREA	LE. AND
				THE T27N R	11W
14. PERMIT NO.	15. ELEV	ATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
11. IBRIII IV.		6247 GR		San Juan	NM
16.	Check Appropriate	pox to indicate the	ature of Notice, Report, or C	UENT REPORT OF:	[- -]
TEST WATER SHUT-OFF	PULL OR AL	TER CASING	WATER SHUT-OFF	REPAIRING W	
FRACTURE TREAT	MULTIPLE C	OMPLETE	FRACTURE TREATMENT	ALTERING CA	11
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMEN	T*
REPAIR WELL	CHANGE PLA	ANS	(Other)(Note: Report_results	of multiple completion of	n Well
(Other)			d toll and due partinent dates	letion Report and Log for	of starting an
17. DESCRIBE PROPOSED OR C proposed work. If w nent to this work.) •	OMPLETED OPERATIONS (Urell is directionally drille	d, give subsurface locati	details, and give pertipent dates, ons and mensured and true vertic	al depths for all markers	and zones perti
-30-90 We propose	to repair hole	in casing with	n a cement squeeze.		
	!		图 经收益		
	ì				
					•
					•

OIL COM. DIV. YDIST. 3



18. I hereby certify that the foregoing is true and correct signed that Maly	TITLE Engineering	Tech DATE 9/27/90
(This space for Federal or State office use) APPROVED BY	TITLE	APPROVED
		OCT 0 9 1990 Ken Townsend

*See Instructions on Reverse Side NMOCD

FOR AREA MANAGEN