

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

COPY
Extra

February 18, 1999

Oil Conservation Division

State of New Mexico
1000 Rio Brazos Road
Aztec, NM 87410
Attn: Charles Perrin

INVOICE #1463-A

Rig #6

For re-entry and subsequent plugging and abandonment of the **Table Mesa #26** well, which is located in the NW, Sec. 03, T-27-N, R-17-W, San Juan County, NM.
This work was done under an emergency basis, Contract Number: _____

Cost Summary:

Line #1 - Double drum pulling unit:

2-15-99	Rig P&A	3.0 hours x \$152/hr	\$ 456.00
	Field Supervisor	1 day	\$ 340.00
2-16-99	Full Package	9.5 hours x \$172/hr	\$ 1,634.00
	Field Supervisor	1 day	\$ 340.00
	1 - 2-3/8" Stripping Rubber		\$ 70.00
2-17-99	Rig P&A	10.0 hours x \$152/hr	\$ 1,520.00
	Field Supervisor	1 day	\$ 340.00
2-18-99	Rig P&A	1.00 hours x \$152/hr	\$ 152.00
Total Line #1 Cost			\$ 4,852.00

Line #2 - Move-in, move-out charges (Transportation):

02-16-99	#1 Haul swivel, water tank and mud pit to loc,		
	Unit #151	5.5 hours at \$62.00/hr	\$ 341.00
	#2 Haul drill collars & 2-3/8" tubing workstring to loc.		
	Unit #141	5.5 hours at \$62.00/hr	\$ 341.00
Total Line #2 Cost:			\$ 682.00

Line #3 - Location and access preparation (Backhoe, Welder, etc.)

02-15-99	#3 Headrick Backhoe # 5711		
	Backhoe	4.5 hours at \$ 45.00/hr	\$ 202.50
	#4 A-Plus Welder, #1476		
	Unit 15	7.0 hours at \$35.00/hr	\$ 245.00
Total Line #3 Cost:			\$ 447.50

Line #4 - Rig Crew Travel Time:

2-15, 16, 17;	3 - Days at \$90.00 per day	\$ 270.00
---------------	-----------------------------	-----------

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

February 18, 1999

Page 2
New Mexico Oil Conservation Division
Table Mesa #26

Rig #6

INVOICE #1463-A

Cost Summary Continued:

Line #5 - Water Truck:

2-16-99 #a	Haul 2 loads water to location;		
	Unit #155	5.0 hours at \$44.00/hr	\$ 220.00
2-17-99 #b	Haul 1 load water to location;		
	Unit #155	2.0 hours at \$44.00/hr	\$ 88.00
	3 Loads of City water at \$20/load		\$ 60.00
Total Line #5 Cost:			\$ 368.00

Line #6 – Perforate squeeze holes:

2-17-99	Perforate 3 HSC squeeze holes at 500'	\$ 490.00
	Perforate 3 HSC squeeze holes at 75'	\$ 490.00
Total Line #6 Cost:		\$ 980.00

Line #7 - Cement Cost:

Plugs: 35 sxs, 20 sxs, 28 sxs, and 3 sxs;		
Total Cement: 86 sxs at \$9.90/sx	\$ 851.40	
Total Line #7 Cost:		\$ 851.40

Line #8 – Pump Charge Costs:

2-17-98 Plugs #1, #2, #3 x \$500/plug	\$ 1,500.00	
Total Line #8 Cost:		\$ 1,500.00

Line #9 – Tubing work string,:

2/16, 2/17 = 2 days of 1350' x .23/ft/day	\$ 310.50	
Total Line #9 Cost:		\$ 310.50

Line #10 – Third Party Charges:

2-15-99 #5a	Drill Bit & Supply, #7764		
	5 bits for project	\$ 945.00	
2-16-99 #5b	Rig Equipment, #00513		
	Pit liner, PVC	\$ 76.41	
Total Third Party Charge Cost:		\$ 1,021.41	

Line #11 – Clean up location and P&A marker:

02-15-99 #6	Headrick Backhoe # 5713		
	Backhoe	3.0 hours at \$ 45.00/hr	\$ 135.00
02-18-99	P&A Marker		\$ 100.00
	#6b A-Plus Welder: install P&A marker		
	Unit #15	2.0 hours at \$35.00/hr	\$ 70.00
Total Line #11 Cost:			\$ 305.00

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

February 18, 1999

Page 3
New Mexico Oil Conservation Division
Table Mesa #26

Rig #6

INVOICE #1463-A

COST SUMMARY:

=====

Line #1 - Double drum pulling unit, A and B:	\$ 4,852.00
Line #2 - Move-in, move-out charges	\$ 682.00
Line #3 - Location and access preparation:	\$ 447.50
Line #4 - Rig Crew Travel Time:	\$ 270.00
Line #5 - Water Truck:	\$ 368.00
Line #6 - Perforate 2 to 4 squeeze holes in well:	\$ 980.00
Line #7 - Cement:	\$ 851.40
Line #8 - Pump Charge:	\$ 1,500.00
Line #9 - Tubing work string,	\$ 310.50
Line #10 - Third Party Charges:	

Total Third Party Charges \$ 1,021.41

Handling Fee 10% \$ 102.14

Total Line #10 Cost: \$ 1,123.55

Line #11 - Location clean up & dry hole marker \$ 305.00

=====

TOTAL \$ 11,689.95

TAX @ 5.9375% \$ 694.09

=====

THANK YOU

TOTAL DUE

\$ 12,384.04

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

Date 2-15-99

Well No. # 26 Location TABLE mesa Company NMOC D
TABLE mesa P/A Project

Fuel & Motor Oil _____ Water Hauled _____
Rental Equipment _____ Cement Retainers _____
Cementing _____
Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	95436	
Operator	Sam Stuart	25	25389	3
Helper	Victor Celis			3
Helper	Robert Velasquez			3
Helper	Deey Hearn			3

Date _____

14471

Rig No 6

Date 2-16-99

Well No. TABRE mesa #26 Location Sec 3, T 27N, R 12W Company NIMCO, D
TABRE mesa P/A Project

CH1212 Lucia

1-2 $\frac{3}{8}$ " Shipping Rubber

w/ DAMOCD on
hoc

Fuel & Motor Oil 60g rly 6 30g PT105 Water Hauled 2-hds A-Plus

Rental Equipment _____ Cement Retainers _____

Cementing

Wireline

9 1/2 hrs Package

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	95555	
Operator	Sam Stuart	20		11
Helper	Victor Celis			11
Helper	Robert Velasquez			11
Helper	Doug Hearn	155		11

Date 2-16-99

Daily Report

A - PLUS WELL SERVICE

14473

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211Rig No 6Date 2-17-99Well No TABLA MESA #26 Location Sec 3, T27N, R17W Company NMOCEDTABLA MESA P/A Project

FROM	TO	DESCRIPTION OF OPERATION
5:30	5:45	load supplies
5:45	7:00	DRIVE TO HOLE + Held safety meeting
7:00	8:00	Pick-up - 3' plugging sub, TIH w/45 jts 2 3/8 + tag w/20' stick-out, lay 1st down, pick-up 10' sub.
8:00	8:30	load hole w/4 B3LS Pump Plug #1 w/35 SXS
8:30	12:30	B-cement 15-4" (1430-1130) TOL 1130 w/220 cal. lay down 8 jts standback 18 stans
12:30		WOL
12:30	1:00	TIH w/37 jts tag w/25' stick-out tagged cement at 1155
1:00	1:30	STANDBACK 9 stans lay down 18 jts
1:30	1:45	P/T 5 1/2 csg to 300 PSI Held OK
1:45	2:00	Perf at 500' w/3 shots 3 1/8 HSC
	2:00	Attempted to pump into squeeze holes
	2:15	unable to, pumped up to 500 #
2:15	2:45	TIH w/18 jts
2:45	3:00	load hole Pump Plug #2 w/20 SXS B-cement 15-4" (575-402) TOL 402
3:00	3:15	lay down 18 jts 2 3/8 tag
	3:15	Perf at 75' w/3 shots 3 1/8 HSC
	3:15	attempted to pump into squeeze holes, unable to
	3:15	pumped up to 500 PSI
3:15	3:30	Pick-up 5 jts
	3:30	load hole Pump Plug #3 w/25 SXS B-cement 15-4" (159-surface) circulate 1 B3L good cement shut in
3:30	5:00	ND BUP + rig down rig + rig pit
	5:00	drain-up SDFD

Charlie Peccan w/ NMOCED on loc.

Fuel & Motor Oil _____ Water Hauled 1-Hd A-Plus
 Rental Equipment _____ Cement Retainers void # 14472
 Cementing Plug #1 35 SXS Plug #2 20 SXS Plug #3 28 SXS
 Wireline (1) 500' 3-3/4 HSC (2) 75' 3-3/4 HSC

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	95679	10 1/2
Operator	Sam Stuart	20	25641	12 1/2
Helper	Victor Celis			12 1/2
Helper	Robert Velasquez			12 1/2
Helper	Darryl Hines			12 1/2

14474

Date 2-18-99

TAJIR MESA P/A Project

SDED

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	95788	
Operator	Sam Stewart	20	25776	11 1/2
Helper	Victor Celis			11 1/2
Helper	Robert Velasquez			11 1/2
Helper	Darryl Hansen	155		12

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

1441

Date: 2/16/99

Truck #: 187

Event: #1	From:	To:	Hours
Start: 0600	What: pr trip		1/2
Stop: 0630	Charge to:		
Event: #2	From:	To:	
Start: 0630	What: haul pit #200, Rem #3 F.T #214 + cables in 141) Swivel #2		2
Stop: 0830	Charge to: NMCCO		
Event: #3	From: Aplus Fmt	To: Table Mesa	
Start: 0830	What: Unwind a spot on loc. Dr To loc.		2
Stop: 1030	Charge to: NMCCO		
Event: #4	From: Table Mesa	To: Aplus Fmt	
Start: 1030	What: Return Fmt		1 1/2
Stop: 1200	Charge to:		
Event: #5	From: Aplus Fmt	To: Jackson #26	
Start: 1200	What: haul pit #80 + ceper #3 + 15 1st 2 3/4 tubing + 12 1st 3/4 Rods		1
Stop: 1300	Charge to:		
Event: #6	From:	To:	
Start: 1300	What: Dr To loc & unwind a spot		9 1/2
Stop: 1530	Charge to:		
Event: #7	From: Jackson #26	To: Aplus Fmt	
Start: 1530	What: Return Fmt		1 1/2
Stop: 1700	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
Driver:	John McElveta		11
Diesel:	Helper John Kenyon Irvin		
Oil:	NM MILES:	CO MILES:	UT MILES:
Remarks:	NMCCO TABLE MESA #26		
Events	2,3,4 Haul mud pit and Water Tank to location on & spot.		

5 1/2

#1

5 1/2 hrs

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499

505-325-2627

1477

Date: 2-16-99

Truck #: 141

Event: #1	From:	To:	Hours
Start: 0600	What: PRE TRIP		1/2
Stop: 0630	Charge to: A-PLUS		
Event: #2	From:	To:	Hours
Start: 0630	What: LOAD - TRAILER - P.V. DRILL COLLARS AT WEATHER FORD		2 1/2
Stop: 900	Charge to: NM OCD		
Event: #3	From:	To:	Hours
Start: 900	What: SPOT FLOAT UNLOAD TOOLS	TABLE MESA	1 1/2
Stop: 10:30	Charge to: NM OCD		
Event: #4	From:	To:	Hours
Start: 10:30	What: ROAD IN	APLUS	1 1/2
Stop: 12:00	Charge to: NM OCD		
Event: #5	From:	To:	Hours
Start: 12:00	What: LUNCH BREAK		1/2
Stop: 1230	Charge to: CHUCK LEZZE		
Event: #6	From:	To:	Hours
Start: 12:30	What: MAKE DRY HOLE MARKER - MAKE ANCHER - FUEL OIL 141		4 1/2
Stop: 5:00	Charge to: A-PLUS		
Event: #7	From:	To:	Hours
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	Hours
Start:	What:		
Stop:	Charge to:		
	Driver: Chuck Lezze		10 1/2
Diesel:	Helper		
Oil:	NM MILES: 76	CO MILES: UT MILES:	
Remarks:	NM OCD TABLE MESA #26 23 1/2" Work Strings on float w/ Load drill collars @ Weatherford Dive to location - Spot float, unload handling tools Return to yard		

5 1/2

#2

5 1/2 hrs

New Mexico

1. 元

B. H. Randol

CUSTOMER'S ORDER NO. #841		DEPT.	DATE:
#126 #1	#Table Mesa	Sig #6	2/15/99
NAME: A-Plus Well Service			
ADDRESS: Farmington, New Mexico			
CITY, STATE, ZIP			

SOLD BY:	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE RTD.	PAID OUT
-----------------	-------------	---------------	---------------	-----------------	------------------	-----------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
4 1/2 hr	(Backhoe Rent) Dig Pit	45 ⁰⁰	202 50
	for Drill out & PTA Set		
	for Anchors Dig out well		
	head Cover Back after welder		
	finished (Eastern Pet #26)		
2 hr	(Backhoe Rent) Trench	45 ⁰⁰	135 00
	water away from well		
	+ Dig small pit to pump		
	water out for PTA & Drill		
	cut operations (#1)		
2 hr	(Backhoe Rent) Trench	45 ⁰⁰	90 00
	water away from well		
	(table #8A # 8A)		
	Total		427 50

RECEIVED BY: Bob R. M.

#3

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

1476

Date: 2-15-99

Truck #: 15

Event: #1	From: A-PLUS YARD To:	Hours
Start: 0600	What: PREP WORK	1 1/2
Stop: 0630	Charge to: A-PLUS	
Event: #2	From: A-PLUS To:	
Start: 0630	What: LOAD WELDER SUPPLIES TO WELD AND 4 RIG ANCHORS	1 1/2
Stop: 0800	Charge to: NM O C D	
Event: #3	From: A PLUS To: TABLE MESA #26	
Start: 0800	What: ROAD OUT	1 1/2
Stop: 0930	Charge to: NM O C D	
Event: #4	From: TABLE MESA To:	
Start: 0930	What: DIG OUT 5'x5' DEEP CUT OFF PIPE - WELD ON 5'x5' PIPE	2 1/2
Stop: 1200	Charge to:	
Event: #5	From: TABLE MESA To: A-PLUS YARD	
Start: 1200	What: ROAD IN	1 1/2
Stop: 130	Charge to: NM O C D	
Event: #6	From: To:	
Start: 130	What: WORK ON 155 DUMPER BUTS - CLUTCH AND BRAKE - WASH	3 1/2
Stop: 500	Charge to:	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
Driver:	Chuck Lutz	
Diesel:	Helper	
Oil:	NM MILES: 76 CO MILES: UT MILES:	
Remarks:		11
Events	NM O C D TABLE MESA #26	
2, 3, 4, 5	Welder - load supplies, drive to location, weld 5'x5' collar onto casing stub. Return to town	

7 hrs

#4

7 hrs

Artus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

1086

Date: 2-16-99

Truck #: 155

Event: #1	From: Yard	To: Yard	Hours
Start: 5:30	What: Pre-Trip		
Stop: 6:00	Charge to: A+		1/2
Event: #2	From: Yard	To: Browning Parkway	
Start: 6:00	What: Load		1/2
Stop: 6:30	Charge to: NMOC		
Event: #3	From: Browning Parkway	To: Table Mesa #26	
Start: 6:30	What: Travel		1 1/2
Stop: 8:00	Charge to: NMOC		
Event: #4	From: Table Mesa #26	To: Murry Thruway	
Start: 8:00	What: 1 Load		3
Stop: 11:00	Charge to: NMOC		
Event: #5	From: Table Mesa #26	To: Yard	
Start: 3:30	What: Travel		1 1/2
Stop: 5:00	Charge to: NMOC		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
Driver:	Dong Han		
Diesel:	Helper		
Oil:	NM MILES: 130	CO MILES:	UT MILES:
Remarks:	NMOC		7
	TABLE MESA #26		
	Haul water to locaters		

5 hrs

#2

5 hrs.

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

1087

Date: 1-17-99

Truck #: 155

Event: #1	From: <u>Yard</u>	To: <u>Yard</u>	Hours
Start: <u>5:30</u>	What: <u>Pre-Trip</u>		
Stop: <u>6:00</u>	Charge to: <u>A+</u>		<u>1/2</u>
Event: #2	From: <u>Yard</u>	To: <u>Browning Pkwy</u>	
Start: <u>6:30</u>	What: <u>Load</u>		
Stop: <u>7:00</u>	Charge to: <u>NMOC</u>		<u>1/2</u>
Event: #3	From: <u>Browning Pkwy</u>	To: <u>Table Mesa 26</u>	
Start: <u>7:00</u>	What: <u>Travel</u>		
Stop: <u>8:30</u>	Charge to: <u>NMOC</u>		<u>1 1/2</u>
Event: #4	From: <u>Table Mesa #26</u>	To: <u>Yard</u>	
Start:	What: <u>Travel</u>	<u>left on hoc.</u>	<u>1 1/2</u>
Stop:	Charge to: <u>NMOC</u>		
Event: #5	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
Driver:	<u>Doug Hen</u>		
Diesel:	Helper		
Oil:	NM MILES: <u>80</u>	CO MILES: _____	UT MILES: _____
Remarks:	<u>NMOC Table Mesa #26</u>		
	<u>Haul 1 load water</u>		

2 hrs

#6

2 hrs



DRILL BIT & SUPPLY✓✓

P.O. BOX 1319 (660 S. DUSTIN RD.)
FARMINGTON, NEW MEXICO 87499
PHONE: 505-326-2679 FAX: 505-326-2670

INVOICE 7764

CUSTOMER ORDER NUMBER _____ DATE 2-15-99

SOLD TO A Plus Well Service

ADDRESS Tabl2 Mesa P/A Project Rig b

DELIVERED TO _____

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	4 3/4 RR TOOTH BIT	225.00	225.00
1	4 1/2 RR # ST0414		
1	4 1/2 RR TOOTH BIT	225.00	225.00
	# 87739		
1	3 7/8 RR TOOTH BIT	200.00	200.00
	# H94882		
1	3 1/2 NEW TOOTH	295.00	295.00
	T2 # T2383		
	SALES TAX		56.11
RECEIVED BY: <u>Bill Hall</u>		TOTAL	\$1001.11

#52

TERMS: PLEASE PAY FROM INVOICE. NO STATEMENT WILL BE SENT. INTEREST
CHARGED AT THE RATE OF 1.5% PER MONTH ON ACCOUNTS UNPAID
AFTER 30 DAYS.

Delivery Ticket

S
O
L
D
T
O

0005000
Amplus Well Service
P.O. Box 1979
Farmington, NM 87499

Date: 02/16/99
Page: 1
Salesperson: 2
Terms: Net 30 days
Ship Via: Counter Picket
D.T. No.: 000513

P.O. No.:

Quan.	Item No:	Description	Unit Price	Disc Amt.	Ext Price
-------	----------	-------------	------------	-----------	-----------

Rig #4
Ordered By: Bill Randall

1	7001936	3-1/2" Gs Bnd 15.50W X 12" K-S 5 Casing Nipple	180.29	108.17-	\$72.12
Discount Is 60%					

Table Mesa #24

#56



RIG EQUIPMENT & SUPPLY COMPANY

P. O. BOX 3128
FARMINGTON, NEW MEXICO 87499
TELEPHONE (505) 327-4927

Order By:

Bill Randall

Sub Total	\$72.12
Tax	\$4.29
Total Sale	\$76.41
Amount Received	\$0.00

5713

O.C.P.

5.1.4.5

Bill Rindel

CUSTOMER'S ORDER NO.		DEPT.	DATE:
Table Mesa #13, Eastern Pk #26		Rtg #6	2/17/98
NAME:			
A-Plus Well Well Service			
ADDRESS:			
Farmington, New Mexico			
CITY, STATE, ZIP			

SOLD BY:	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE RTD.	PAID OUT
-----------------	-------------	---------------	---------------	-----------------	------------------	-----------------

QUANTITY	DESCRIPTION			
4 hr	(Backhoe Rent) Dig Pit for Drill out & PTA, Set <u>four</u> Anchors, Dig out well, move Cmt Block for Pump Jack (Table Mesa #13)	45 ⁰⁰	180	00
3 hr	(Backhoe Rent) Cover Pit after PTA & Dry up (Eastern Pit #26)	45 ⁰⁰	135	00
2 hr	(Backhoe Rent) Dig out three other wells #3 #8 #8A Total	45 ⁰⁰	135	00
			450	00

RECEIVED BY: Bill Raloff

#62

KEEP THIS COPY FOR YOUR RECORDS

©1998 REDIFORM® 5L320

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499

505-325-2627

1101

Date: 2-18-99

Truck #: 15

Event: #1	From:	To:	Hours
Start: 0600	What: LOAD WELDER AND SUPPLIES		
	CUT PIPE FOR DRY HOLE MARKERS		1
Stop: 0700	Charge to: NMOC D		
Event: #2	From: A-PLUS	To: TABLE MESA #13	1
Start: 0700	What: ROAD OUT		
Stop: 0800	Charge to: NMOC D		
Event: #3	From:	To:	
Start: 0800	What: CUT OFF DRY HOLE MARKER CLEAN		2
	AND REPAIR THREADS MAKE D.H.M. T.M. #13		
Stop: 1000	Charge to: NMOC D		
Event: #4	From:	To:	
Start: 1000	What: CUT 8 5/8 PIPE W COLLAR BEVEL AND		
	WELD TO STAVE T.M. #3 MAKE D.H.M.		2
Stop: 1200	Charge to: NMOC D		
Event: #5	From:	To:	
Start: 1200	What: DIG OUT REMOVE WATER LOCATE HOLE		1 1/2
	TABLE MESA #2		
Stop: 1:30	Charge to: NMOC D		
Event: #6	From:	To:	
Start: 1:30	What: WELD ON DRY HOLE MARKER TABLE		
	MESA #26 V OUT 3 OTHER WELLS FOR PREP		1
Stop: 2:30	Charge to: NMOC D		
Event: #7	From: TABLE MESA #26	To: A-PLUS YARD	
Start: 2:30	What: ROAD IN		1
Stop: 3:30	Charge to: NMOC D		
Event: #8	From:	To:	
Start: 3:30	What: UNLOAD WELDER SUPPLIES ETC. GET		1
	12 1/2 PIPE AND 7" PIPE FOR WELLS 8-		
Stop: 4:30	Charge to: NMOC D	IM. 1 + 8 A	
	Driver: CHARLES LEWIS		10 1/2
Diesel:	Helper		
Oil:	NM MILES: 76	CO MILES: _____	UT MILES: _____
Remarks:	NMOC D Table Mesa #26		
	Install P.H. Marker		

#26

6h

2 hrs