

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

COPY
EXTRA

February 24, 1999

Oil Conservation Division
State of New Mexico
1000 Rio Brazos Road
Aztec, NM 87410

Attn: Charles Perrin

INVOICE #1463-B

Rig #6

For re-entry and subsequent plugging and abandonment of the **Table Mesa #13** well, which is located in the NE, Sec. 03, T-27-N, R-17-W, San Juan County, NM.

This work was done under an emergency basis, **Project Number:** _____

Cost Summary:

Line #1 – Double drum pulling unit:

2-18-99 Rig P&A	10.0 hours x \$172/hr	\$ 1,720.00
Field Supervisor		\$ 340.00
1 – 2-3/8" Stripping Rubber		\$ 70.00
2-19-99 Rig P&A	10.0 hours x \$152/hr	\$ 1,520.00
Field Supervisor		\$ 340.00
2-22-99 Rig P&A	3.5 hours x \$152/hr	\$ 532.00
Field Supervisor		\$ 340.00
2-23-99 Rig P&A	1.0 hour x \$152/hr	\$ 152.00
Total Line #1 Cost		\$ 5,014.00

Line #2 – Move-in, move-out charges (Transportation):

02-18-99 #7 Move tank, P/S, float to new location.		
Unit #141	6.5 hours at \$62.00/hr	\$ 403.00
02-22-99 #8 Move water tank to new well then take tubing workstring to town for safe keeping.		
Unit #141	6.5 hours at \$62.00/hr	\$ 403.00
Total Line #2 Cost:		\$ 806.00

Line #3 –Location and access preparation (Backhoe, Welder, etc.)

02-17-99 #9 Headrick Backhoe, #5713		
Backhoe	4.0 hours at \$ 45.00/hr	\$ 180.00
02-18-99 #10 Welder: cut off old marker, weld 8-5/8" stub;		
Unit 15	4.0 hours at \$35.00/hr	\$ 140.00
02-19-99 #11 Welder: install collars and weld pipe		
	7.5 hours at \$35.00/hr	\$ 262.50
Total Line #3 Cost:		\$ 582.50

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211
February 24, 1999

Page 2
New Mexico Oil Conservation Division
Table Mesa #26

Rig #6

INVOICE #1463-B

Cost Summary Continued:

Line #4 - Rig Crew Travel Time:

2-18, 19, 22; 23- Days at \$90.00 per day \$ 360.00

Line #5 - Water Truck:

2-18-99 #c Transfer water to new location; return to yard
Unit #155 3.0 hours at \$44.00/hr \$ 132.00

Line #6 - Perforate squeeze holes:

2-19-99 Perforate 3 HSC squeeze holes at 500' \$ 490.00

Line #7 - Cement Cost:

Plugs: 25 sxs, 5 sxs, 214 sxs, and 24 sxs;
Total Cement: 268 sxs at \$9.90/sx \$ 2,653.20

Line #8 - Pump Charge Costs:

2-18-99 plug #1 \$ 500.00
2-19-99 plugs #1b and #2 at \$500/plug \$ 1,000.00
Total Line #8 Cost: \$ 1,500.00

Line #9 - Tubing work string,:

2-18-99 2 days of 1338' x .23/ft \$ 307.74

Line #10 - Third Party Charges:

2-18-99 #12 Construction Supply, 2108388
Reinforced Poly film, pit liner \$ 133.34

Line #11 - Clean up location and install a P&A marker:

2-22-99 #13 Headrick Backhoe, #5715
Backhoe 3.0 hours at \$ 45.00/hr \$ 135.00
2-22-99 P&A Marker \$ 100.00
Total Line #11 Cost \$235.00

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

February 24, 1999

Page 3
New Mexico Oil Conservation Division
Table Mesa #26

Rig #6

INVOICE #1463-B

COST SUMMARY:

=====

Line #1 - Double drum pulling unit:		\$ 5,014.00
Line #2 - Move-in, move-out charges		\$ 806.00
Line #3 - Location and access preparation:		\$ 582.50
Line #4 - Rig Crew Travel Time:		\$ 360.00
Line #5 - Water Truck:		\$ 132.00
Line #6 - Perforate:		\$ 490.00
Line #7 - Cement:		\$ 2,653.20
Line #8 - Pump Charge:		\$ 1,500.00
Line #9 - Tubing work string:		\$ 307.74
Line #10 - Third Party Charges:		
Total Third Party Charges	\$ 133.34	
Handling Fee 10%	\$ 13.33	
Total Line #10 Cost:		\$ 146.67
Line #11 - Clean up location and dry hole marker		\$ 235.00
		=====
TOTAL		\$ 12,227.11
TAX @ 5.9375%		\$ 725.98
		=====
THANK YOU	TOTAL DUE	\$ 12,953.09

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211Rig No 6Date 2-18-99Well No TABLE MESA #13 Location Sec 3, T27N, R17W Company NMOCED
TABLE MESA P/A Project

FROM	TO	DESCRIPTION OF OPERATION
5:30	5:45	Load supplies
6:45	7:00	DRIVE TO LOC. Held safety meeting (Hot-work)
7:00		Rode Rig & equip. to loc
	10:30	RU Rig, NU BOP's & test, RU equip to drill
10:30		began drilling w/4 3/4 bit & 1 drill collar (3 1/2')
	12:45	drilled about 6' & fell thru
12:45		ND power swivel, Pick-up 41 fts 2 3/8" & 1 drill collar.
	2:00	Tag at 1338'
2:00	2:30	stand back 20 stands, lay down 1-drill collar
2:30	3:00	Pick-up 3' plugging sub, THT w/42 fts & tag
3:00		load hole & circulate w/10 BBLs Pump Plug #1 w/25 SXS
	3:30	B-cement 15-5" (1338-1160) TOL 1110,
3:30	4:00	lay down 6 fts, stand back 18 stands
		shut-in well, drain-up
		SDFD
4:00	5:00	Fence pit on TABLE MESA #3
		put 3 SXS around Dry hole marker on
		Table Mesa #26
		1 - 2 3/8" Stripping Rubber.

Fuel & Motor Oil 30g. #121
30g. Rig 6, 30g. P.T. 105

Water Hauled

Rental Equipment

Cement Retainers

Cementing Plug #1 25 SXS

Wireline

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	95788	
Operator	Sam Stewart	20	25776	11 1/2
Helper	Victor Celis			11 1/2
Helper	Robert Velazquez			11 1/2
Helper	Darryl Harden	155		12

1624

Date 2-19-99

TABLE MESH P/A Project

Fuel & Motor Oil _____ Water Hauled _____ void #14475
Rental Equipment _____ Cement Retainers _____
Cementing Plug 1B 55x3 Plug #2 214545
Wireline 500' 3-3/4 HSC

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	95944	
Operator	Sam Stuart	20	25971	11 1/2
Helper	Victor Celis			11 1/2
Helper	Doug Heuen	143		12 1/2
Helper				

14627

Date 2-22-99

FROM	TO	DESCRIPTION OF OPERATION
5:30	5:45	load supplies
5:45	7:00	DRIVE TO LOC.
7:00	8:00	wait on Navajo Police, held safety meeting (1 st Aid)
8:00		ck cement in 5 1/2" down 7ft. WD BOP's
		dog-out wellhead, cut all csqs
		install dry hole marker cement in 10 3/4" full
		W/24 sxs B-cement cement in 8 3/4" down 6'
	10:00	fill to surface cement in 7" down 5'
10:00	10:30	Back-up pit & PT105
		shut-down
		too winding, to rig-down

3 1/2 hrs

Date _____

11622

Rig No 6

Date 2-23-99

Well No T41342 Mesa # 13 Location Sec. 3, T27N, R17W Company WMCCLD

TABLE mesa P/A Project

Fuel & Motor Oil _____ Water Hauled _____
Rental Equipment _____ Cement Retainers _____
Cementing _____
Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12		
Operator	Sam Stuart	20		
Helper	Vinton Celis			2 1/2
Helper	Robert Velasquez			2 1/2
Helper	Danny Heaven			2 1/2

Date _____

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499

505-325-2627

1479

Date: 2 18 99

Truck #: 141

Event: #1	From:	To:	Hours
Start: 0600	What: pre trip		1/2
Stop: 0630	Charge to:		
Event: #2	From:	To:	Hours
Start: 0630	What: Dr to loc	Table Mesa 21	1
Stop: 0730	Charge to: NMOC		
Event: #3	From:	To:	Hours
Start: 0730	What: Mesa 21, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000		3 1/2
Stop: 1100	Charge to: NMOC		
Event: #4	From:	To:	Hours
Start: 1100	What: Return Stopped by P.C.T.		2
Stop: 1300	Charge to: NMOC		
Event: #5	From:	To:	Hours
Start: 1300	What: Road 12 1/2 3/4 Rods + 12 1/2 2 3/4 Rods + Dr to loc. inland	Jackson 41	2
Stop: 1500	Charge to: Hollisvahan		
Event: #6	From:	To:	Hours
Start: 1500	What: Return from	Aplus Farm	1 1/2
Stop: 1630	Charge to: Hollisvahan		
Event: #7	From:	To:	Hours
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	Hours
Start:	What:		
Stop:	Charge to:		
	Driver: John McElister		11 1/2
Diesel:	Helper: John Kevin Irvine		11 1/2
Oil:	NM MILES: 186 CO MILES: UT MILES:		
Remarks:			
Event #4	Stopped by P.C.T on Rd 36 on gas asked why I was using this Rd. along w/ 1 heavy truck		
# 2,3	NMOC Table Mesa #13		
4	move tank, P/S, float to new location		

#7

6 1/2

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

1444

Date: 2 22 99

Truck #: 141

Event: #1	From:	To:	Hours
Start: 0530	What: prz trip		1/2
Stop: 0540	Charge to:		
Event: #2	From: Aplus FMT	To: Table Mesa 13	
Start: 0530	What: Load F.T. 351 + more to covered		2
Stop: 0730	Charge to: NMOCID		
Event: #3	From: Table Mesa 13	To: Table Mesa 3	
Start: 0730	What: Mixed F.T. 214; Mixed #2 float w/ work string		2 1/2
Stop: 1000	Charge to: NMOCID		
Event: #4	From: Table Mesa #3	To:	
Start: 1000	What: Return FMT with float 98 + work string		2
Stop: 1200	Charge to: NMOCID		
Event: #5	From:	To:	
Start: 1200	What: Load casing on float w/ work string		1/2
Stop: 1230	Charge to: NMOCID		
Event: #6	From: Aplus FMT	To: Jackson pad #1	
Start: 1230	What: Dr To loc.		1
Stop: 1330	Charge to: Hollisvachan		
Event: #7	From:	To:	
Start: 1330	What: Pump mud pit + load pit #80 + Cooper #3		2
Stop: 1530	Charge to:		
Event: #8	From: Jackson pad #1	To: Aplus FMT	
Start: 1530	What: Return FMT + work		1 1/2
Stop: 1700	Charge to: Hollisvachan		
Driver:	<u>John McAlister</u>		1 1/2
Diesel:	Helper		
Oil:	NM MILES: <u>110</u>	CO MILES: _____	UT MILES: _____
Remarks:			
Event	NMOCID TARGE MESA #3		
2, 3, 4	More water tank, float to town for safe keeping		

#8

6 1/2 hrs.

5713

O.C.P.

Bill Randel

CUSTOMER'S ORDER NO.		DEPT.	DATE:
Table Mesa #13 Eastern Pet #26		Rtg H/L6	2/17/90
NAME:			
A-Plus Well Well Service			
ADDRESS:			
Farmington, New Mexico			
CITY, STATE, ZIP			

SOLD BY:	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE RTD.	PAID OUT
-----------------	-------------	---------------	---------------	-----------------	------------------	-----------------

[illegible]

#9

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

1101

Date: 2-18-99

Truck #: 15

Event: #1	From:	To:	Hours
Start: 0600	What: LOAD WELDER AND SUPPLIES		
	CUT PIPE FOR DRY HOLE MARKERS		1
Stop: 0700	Charge to: NM OCD		
Event: #2	From: A-PLUS	To: TABLE MESA #13	1
Start: 0700	What: ROAD OUT		
Stop: 0800	Charge to: NM OCD		
Event: #3	From:	To:	
Start: 0800	What: CUT OFF DRY HOLE MARKER CLEAN		2
	AND REPAIR THREADS MAKE D.H.M. T.M. #13		
Stop: 1000	Charge to: NM OCD		
Event: #4	From:	To:	
Start: 1000	What: CUT 8 5/8" PIPE W COLLAR BEVEL AND		
	WELD TO STAVE T.M. #3 MAKE D.H.M.		2
Stop: 1200	Charge to: NM OCD		
Event: #5	From:	To:	
Start: 1200	What: DIG OUT REMOVE WATER LOCATE HOLE		1 1/2
	TABLE MESA #2		
Stop: 1:30	Charge to: NM OCD		
Event: #6	From:	To:	
Start: 1:30	What: WELD ON DRY HOLE MARKER TABLE		
	MESA #26 & OUT 3 OTHER WELLS FOR PREP		1
Stop: 2:30	Charge to: NM OCD		
Event: #7	From: TABLE MESA #26	To: A-PLUS YARD	
Start: 2:30	What: ROAD IN		1
Stop: 3:30	Charge to: NM OCD		
Event: #8	From:	To:	
Start: 3:30	What: UNLOAD WELDER SUPPLIES ETC. GET		1
	12 1/2" PIPE AND 7" PIPE FOR WELLS 8-		
Stop: 4:30	Charge to: NM OCD	Im. 1+ - 8A	
	Driver: CHARLES LINZES		10 1/2
Diesel:	Helper		
Oil:	NM MILES: 76	CO MILES: _____	UT MILES: _____
Remarks:	NM OCD TABLE MESA #13		
1, 2, 3	Drive to Loc, X off old Marker,		
	Weld to 8 5/8" casg stub.		
	Welder.		

4 hrs

#10

4 hrs

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

1102

Date: 12-19-99

Truck #: 15-

Event: #	From:	To:	Hours
Start: 0600	What: CUT WELD 13" PIPE FOR		
	TABLE MESA - 8' - 8A' + 1		4.5
Stop: 10:30	Charge to: NM O C D		
Event: #2	From: A-PLUS	To: T.M. 13	
Start: 10:30	What: ROAD OUT TO TABLE		
	MESA - 13		1
Stop: 11:30	Charge to: NM O C D		
Event: #3	From:	To:	
Start: 11:30	What: WELD CASING AND COLLARS		
	ON T.M. 13 LAY DOWN TUBING ON 13		5.5
Stop: 1700	Charge to: NM O C D		
Event: #4	From: T.M. 13	To: A-PLUS YARD	
Start: 1700	What: ROAD IN AND UNLOAD		1
	WELDER AND SUPPLIES FROM 15		
Stop: 1800	Charge to: NM O C D		
Event: #5	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
Driver:	CHARLES LEUZZI		(12)
Diesel:	Helper		
Oil:	NM MILES: 76	CO MILES: _____	UT MILES: _____
Remarks:			
	NM O C D TABLE MESA 13		
2,3,4	Weld collars to casing to make well head for cementing Control		

7 1/2 hrs.

#11

7 1/2 hrs

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

1088

Date: 1-18-99

Truck #: 155

Event: #1	From: Table Mesa 26	To: Table Mesa 13	Hours
Start: 7:00	What: Transfer Water From Table Mesa 26 to Table Mesa 13		1 1/2
Stop: 8:30	Charge to: NMOCD		
Event: #2	From: Table Mesa 13	To: Yard	
Start: 4:00	What: To are!		1 1/2
Stop: 5:30	Charge to: NMOCD		
Event: #3	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #4	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #5	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
Driver:	Darryl Hen		
Diesel:	Helper		3
Oil:	NM MILES: 240	CO MILES: _____	UT MILES: _____
Remarks:			
	NMOCD TABLE MESA #13		
	Transfer Water, Return to yard.		

(C)

3 hrs.



P.O. BOX 1840 • 600 AZTEC BLVD. N.E.
AZTEC, NEW MEXICO 87410
(505) 334-6118 • FAX: 505-334-6084

P.O. BOX 970 • 912 W. BROADWAY
BLOOMFIELD, NEW MEXICO 87413
505-632-3369 • FAX: 505-632-9877

P.O. BOX 1080 • 716 EAST MAIN ST.
FARMINGTON, NEW MEXICO 87499
505-325-2871 • FAX: 505-327-2407

2108383

INVOICE

DATE: 11/14/90

QUANTITY: 1000
UNIT PRICE: \$1.15
TOTAL: \$115.00

TERMS: NET 30
DUE DATE: 12/14/90

P-114
Q-1
W-37
L-2
P-1

DATE: 11/14/90

✓	L #	QUANTITY	DESCRIPTION	CATALOGUE #	UNITS	PRICE/UNIT	AMOUNT
		1000	2x4 S-P-F L-1000 PULL BOLT	48418-PDP		1.15	115.00

DATE: 11/14/90

WE VALUE YOU AS A CUSTOMER. LET US KNOW HOW WE CAN SERVE YOU.

Accounts are due the 10th of the month following purchases. Purchaser agrees to pay a FINANCE CHARGE OF 1.5% per month on unpaid balance. (ANNUAL PERCENTAGE RATE of 18%) or a minimum charge of .50¢ per month. Accounts that have been placed for collection will be charged a \$100.00 collection fee in addition to reasonable attorney fees and collection charges.

Received
By

X

#12

Row Headrick

5715

OCD

Bill Bawde

CUSTOMER'S ORDER NO. Table Mesa # 13, Table Mesa # 10 Rig # 6	DEPT.	DATE: 2/22/99
NAME: A-Plus Well Service		
ADDRESS: Farmedington, New Mexico		
CITY, STATE, ZIP		

SOLD BY:	CASH	C.O.D.	CHARGE	ON ACCT.	DEBITED	PAID OUT
-----------------	-------------	---------------	---------------	-----------------	----------------	-----------------

3 hr	(Backhoe Rent) Cover Pit + Clean up location after P&A (Table Mesa # 13)	45 ⁰⁰	135 ⁰⁰	
3 hr	(Backhoe Rent) Drain water from East side of location Fill in where we moved cut shut out (Table Mesa # 19)	45 ⁰⁰	135 ⁰⁰	
1 1/2 hr	(Backhoe Rent) Drain water From Table Mesa # 8 + # 8A further in to South away from Table Mesa # 19	45 ⁰⁰	67 ⁵⁰	
	Total		337 ⁵⁰	

RECEIVED BY: *[Signature]*

#13